

Report of Survey for Repairs of Engines and Boilers.

No. *24635*
 No. in Reg. Book. *4961* Survey held at *Glasgow* Date, first Survey *Sept. 3rd* Last Survey *Sept. 25th 1879*
 on the *S. S. "Amrapoora"* Master *Stuart*
 Built at *Greenock* When built *1844-7 mo -*
 No. *1619* Owners *British & Burmese Steam Navigation Co. (Limited)* Port belonging to *Glasgow* Classified *100 A1*
2464 Character in Register Book. *4.78*

Diameter of Cylinder *8 40" & 48"* Engines made at *Greenock* When made *1844*
 Length of Stroke *45"*
 Pressure of Steam *65 lbs* By whom made *Greenock Lundry Coy*
 Rated Horse Power *300*

Particulars of Repairs and Examination *Engines, Cylinders & Slide Valve Castings opened and Pistons & Valves, thoroughly overhauled & examined all pumps pipes and connections cleaned & overhauled Crank Shaft Journals, and bearings, examined and overhauled also Connecting Rods Brasses overhauled, Sea Cocks & Valves examined and overhauled in Dry Dock*

Boilers, thoroughly examined and a number of tubes renewed, several rivets in Furnace mouths renewed

The Engines & Boilers are now in good working condition, and eligible in my opinion to remain as classed for twelve months, and to be listed in the Register Book 3 & M. S. 9.79

The Amount of Fee ... £ *1 : 1 : -* received by me, *James Morrison*
 Certificate (if required) ... £ *0 : 0 : -* Oct. 1879
 (Travelling Expenses, if any, £ *-*)

Committee's Minute

18

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Clyde District

Lloyd's Register Foundation

