

ANNUAL SURVEYS.

24674

Rec. 30.9.79

30521 Survey held at London Date, first Survey 19th Sept. Last Survey 19th Sept. 18 79
 in on the S.S. "Tern" Master J. B. Randall
 Book. 609 Tonnage 959 Built at Dundee When built 1875 - 8mo
53 By whom built Gourlay Owners Genl. Stm. Nav. Co.
 Port belonging to London Destined Voyage Rotterdam
 If Surveyed Afloat or in Dry Dock Genl. Stm. Nav. Co. Gridiron

Last Survey, No. 20989 Port of Iron Classed 100A1
 Present Condition of the Good Keels Good
 Decks Good Rivets Good
 Waterways Good Breasthooks and Stemson Good
 Timings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Streakstrakes Good Clamps and Shelves Good
 Sides Good Ceiling Good
 Deck Good Rudder Good
 (Bottom) and Counter Good Coating on bottom Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom cleaned and recoated.

This vessel is now in good condition and eligible in my opinion to be continued as at present classed.

Attention was drawn to the S.S. not being about due, which the owners desire to defer for a short time.

Committee's Minute 3rd October, 1879. Edwards.

Character assigned 100A1 TRW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 363/627/556 Survey held at London Date, first Survey 25th Sept Last Survey 27th Sept. 18 79
 in on the Sad. Stm. "Swift" Master W. Butcher
 g. Book. 323 Tonnage 863/627/556 Built at Stockton When built 1875 - 6mo
 By whom built Pearse Owners Genl. Stm. Nav. Co.
 Port belonging to London Destined Voyage Ostend
 If Surveyed Afloat or in Dry Dock Genl. Stm. Nav. Co. Gridiron

Last Survey, No. 19812 Port of Iron Classed 100A1
 Present Condition of the Good Keels Good
 Decks Good Rivets Good
 Waterways Good Breasthooks and Stemson Good
 Timings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Streakstrakes Good Clamps and Shelves Good
 Sides Good Ceiling Good
 Deck Good Rudder Good
 (Bottom) and Counter Good Coating on bottom Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom cleaned and recoated.

Timbers and 2 strakes of ceiling lifted on each side in fore hold (from fore hatch to fore mast) and Cement &c examined and found good. - The attention of the owners' representative was drawn to the S.S. not being about due, but which, it is understood, the owners desire to defer for a short time. - This vessel is now in good condition and eligible in my opinion to remain as at present classed.

Committee's Minute 3rd October, 1879. Edwards.

Character assigned 100A1 TRW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

IRON 488-0057