

REPORT of SURVEY for REPAIRS, &c.

No. 106

No. in Survey held at

New York

Date, first Survey

(Received at London Office,

Last Survey

18

Reg. Book. 26 on the

New St. Caduceus

Master

J. Satterley
YEAR. MONTH.

TONNAGE under Tonnage Deck

1765

Ditto of Spar Deck, or Avoing Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

1860

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as S^rmer, cut on Bm.

1191

Built at

Newcastle

When built

1874

11

Owners

Hall Bros.

Port belonging to

London

Residence

By whom built

Destined Voyage

If Surveyed Afloat or in Dry Dock

See Report attached

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No.

24035

Port

London

Classed

100A1

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

P.S. Nov-78
7-79

Condition of the

Deck Beams & Fastenings

ms & Fastenings

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper (or Y.M.)

When put on

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Amount of Entry Fee£

Special£

received by me,

18

Certificate (if required)

to be sent as per margin...

Surveyor to Lloyd's Register of British and Foreign Shipping.

Travelling Expenses, if any, £

Committee's Minute

Character assigned

afounded Leany, no the right form

14th October,

18 79.

31st October,

79.

100A1

TRW 14/10/79 TRW



© 2019

Lloyd's Register
Foundation

IRON 488-0338