

# ANNUAL SURVEYS.

No. 4974 Survey held at Glasgow Date, first Survey 9<sup>th</sup> Octr. Last Survey 10<sup>th</sup> Octr. 1879  
 No. in on the S. S. "Summerlee" Master J. B. Smith  
 Reg. Book. 1205 Tonnage 833 Built at Glasgow When built 1877-7 mo.  
 By whom built J. G. Thomsons Owners W. Neilson & Co.  
 Port belonging to Glasgow Destined Voyage Bilboa  
 If Surveyed Afloat or in Dry Dock On Pointhouse Slip and Afloat

Last Survey, No. 23350 Port of Glasgow

Classed 100 A1  
 Years assigned. 4/79  
 Character in Register Book.

Present Condition of the

Decks	<u>Good</u>	<del>Rivets</del> Rivets	<u>Good</u>	
Waterways	<u>do</u>	Breasthooks and Stemson	<u>do</u>	
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>	Windlass and Capstan <u>Good</u>
Upper Deck Beams & Fastenings	<u>do</u>	<del>Transoms</del> of the Frame at the Openings	<u>do</u>	Pumps <u>do</u>
Lower Deck Beams & Fastenings	<u>do</u>	<del>Transoms</del> ditto at other places	<u>do</u>	Boats <u>3 no.</u> <u>do</u>
Planksheers	<u>do</u>	Keelsons	<u>do</u>	Masts, Yards, &c. <u>do</u>
Sheerstrakes	<u>do</u>	<del>Keelsons</del> <u>Securities</u>	<u>do</u>	Condition, how ascertained <u>From deck</u>
Topsides	<u>do</u>	Ceiling	<u>do</u>	Sails <u>Well Found</u>
Wales	<u>do</u>	Rudder	<u>do</u>	Anchors, No. of <u>3 B. 1 S. 2 K.</u>
<del>Plating</del> (Bottom) and Counter	<u>do</u>	<del>Coating</del> <u>Coating</u> When put on <u>Octr 1879</u>	<u>do</u>	Cables <u>Complete</u>
Engine Room Skylights <u>Good</u>		Caulking of	<u>do</u>	Hawsers and Warps <u>Well Found</u>
Coal Bunker, Openings, Lids, &c. <u>Good</u>		Bottom, Deck, & Waterways <u>Good</u>		Standing and Running Rigging <u>Good</u>
General Observations, Opinion as to Class, &c.		Scuppers <u>Good</u>		Cargo and Main Hatchways <u>Good</u>
				Hatches <u>Good</u>

Bottom cleaned examined and re-coated - Steering gear to be worked by steam now fitted. iron comings to cabin sky light raised to about 4 feet above deck. stowage of boats re-arranged. Vessel is in good and efficient condition eligible to remain as classed

Committee's Minute 24th October, 1879.

Character assigned 100

Saml. Laphorn  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) 18

No. 4974 Survey held at Glasgow Date, first Survey 14<sup>th</sup> Octr. Last Survey 14<sup>th</sup> Octr 1879  
 No. in on the S. S. "Waverley" Master Chas. McIntyre  
 Reg. Book. 158 Tonnage 496 Built at Paisley When built 1877-5 mo.  
 By whom built McIntyre Owners W. McLachlan & Co.  
 Port belonging to Glasgow Destined Voyage Coasting  
 If Surveyed Afloat or in Dry Dock On Pointhouse Slip

Last Survey, No. 18402 Port of Glasgow

Classed 90 A1  
 Years assigned. 6/77  
 Character in Register Book.

Present Condition of the

Decks	<u>Good</u>	<del>Rivets</del> Rivets	<u>Good</u>	
Waterways	<u>do</u>	Breasthooks and Stemson	<u>do</u>	Windlass and Capstan <u>Good</u>
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>	Pumps <u>do</u>
Upper Deck Beams & Fastenings	<u>do</u>	<del>Transoms</del> of the Frame at the Openings	<u>do</u>	Boats <u>1 no.</u> <u>do</u>
Lower Deck Beams & Fastenings	<u>do</u>	Ditto ditto at other places	<u>do</u>	Masts, Yards, &c. <u>do</u>
Planksheers	<u>Good</u>	Keelsons	<u>do</u>	Condition, how ascertained <u>From deck</u>
Sheerstrakes	<u>do</u>	<del>Keelsons</del> <u>Securities</u>	<u>do</u>	Sails <u>Well Found</u>
Topsides	<u>do</u>	Ceiling	<u>do</u>	<u>(new sent now supplied)</u>
Wales	<u>do</u>	Rudder	<u>do</u>	Anchors, No. of <u>2 B. 1 S. 1 K.</u>
<del>Plating</del> (Bottom) and Counter	<u>do</u>	<del>Coating</del> <u>Coating</u> When put on <u>Octr 1879</u>	<u>do</u>	Cables <u>Complete</u>
Engine Room Skylights <u>Good</u>		Caulking of	<u>do</u>	Hawsers and Warps <u>Well Found</u>
Coal Bunkers, Openings, Lids, &c. <u>Good</u>		Bottom, Deck, & Waterways <u>Good</u>		Standing and Running Rigging <u>Good</u>
General Observations, Opinion as to Class, &c.		Scuppers <u>Good</u>		Cargo and Main Hatchways <u>Good</u>
				Hatches <u>Good</u>

Bottom cleaned examined and re-coated, 2 new stoppers fitted to Rudder. 3 shifts of ceiling lifted opposite where vessel had grounded, cement repaired, ceiling relaid; Vessel is in good and efficient condition eligible to remain as classed.

Committee's Minute 24th October, 1879.

Character assigned 90

Saml. Laphorn  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) 18



Eligible Allen



© 2019

Lloyd's Register  
Foundation