

ANNUAL SURVEYS.

No. 4505 Survey held at S. Shields Date, first Survey 7 Last Survey 30th Oct 18 79
 No. in on the Iron S. S. Achilles Master M. Jones
 Reg. Book. 82 Tonnage 740 Built at Sunderland When built 1865 2 Mo
 By whom built Lain Owners Fenwick & Co
 Port belonging to London Destined Voyage ✓
 Surveyed Afloat or in Dry Dock Dry Dock
 Last Survey, No. 38542 Port of London Classed GOA.1.
 Years assigned. 10.79 Character in Register Book.

Present Condition of the
 Decks Good Freenails Pist Good
 Waterways D. Breasthooks and Stemson D.
 Comings D. Transoms, Pointers, and Crutches D.
 Upper Deck Beams & Fastenings D. Timbers of the Frame at the Openings D.
 Lower Deck Beams & Fastenings D. Ditto ditto at other places D.
 Planksheers D. Keelsons D.
 Sheerstrakes D. Clamps and Shelves D.
 Topsides D. Ceiling D.
 Wales D. Rudder D.
 Plank (Bottom) and Counter D. Copper or Y.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

Bottom sighted & cleaned. Now supplied 15 feet of 1 3/16 chain. Test 43 9/10 & 61 4/10. Near P. H. J. Hartness Sup^r 22.10.79. One Bower Anchor Ex stock 23.2.14. Test 23.11.3.14. Near P. H. J. Hartness 16.10.79. The above equipment having now been supplied as required by London Report No 38542. She is in my opinion eligible to remain as classed.

Committee's Minute 4th November, 1879 H. Mowbray
 Character assigned GOA.1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) ✓ Paid 18

No. 4505 Survey held at S. Shields Date, first Survey 7 Last Survey 30th Oct 18 79
 No. in on the Iron S. S. Emeraldale Master M. Martin
 Reg. Book. 788 Tonnage 1298 Built at Sunderland When built 1872 11 Mo
 By whom built Short Owners Milburn Bros
 Port belonging to S. Shields Destined Voyage ✓
 Surveyed Afloat or in Dry Dock Dry Dock
 Last Survey, No. 23390 Port of London Classed GOA.1.
 Years assigned. 4.79 Character in Register Book.

Present Condition of the
 Decks Good Freenails Pist Good
 Waterways D. Breasthooks and Stemson D.
 Comings D. Transoms, Pointers, and Crutches D.
 Upper Deck Beams & Fastenings D. Timbers of the Frame at the Openings D.
 Lower Deck Beams & Fastenings D. Ditto ditto at other places D.
 Planksheers D. Keelsons D.
 Sheerstrakes D. Clamps and Shelves D.
 Topsides D. Ceiling D.
 Wales D. Rudder D.
 Plank (Bottom) and Counter D. Copper or Y.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

Bottom sighted, cleaned & repainted. She is now in good and efficient condition, and in my opinion eligible to remain as classed.

Committee's Minute 4th November, 1879 H. Mowbray
 Character assigned GOA.1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) ✓ Paid 18

In am. Port No 38542, herewith returned 11.11.79.

