

REPORT of SURVEY for REPAIRS, &c.

No. 4684

No. in Reg. Book.

Survey held at

Date, first Survey

Last Survey

1879

on the

Master

TONNAGE under Tonnage Deck

Ditto of Spar Deck, or Avoing Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St mer, cut on Bm.

Built at

When built

Owners

Port belonging to

Residence

By whom built

Destined Voyage

Surveyed Afloat or in Dry Dock

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No.

Port

Classed

REPAIRS, OR EXAMINATION AS PER RULE

Vessel placed on blocks in drydock. Bottom keel and rudder found in good condition. One bulwark stanchion found broken and two bent on Portside. One stanchion renewed and two taken out straightened and rivetted. Bottom scraped, chamed and two coats of paint applied.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

General Observations, Opinion as to Class, &c.

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Windlass and Capstan

Pumps

Boats 5 in number

Masts, Yards, &c.

Condition, how ascertained from deck & enquiry.

Sails

Anchors No. of 3 B.A. 2 R. 1/2

Cables port seen

Hawsers and Warps

Standing & Running Rigging

Cargo and Main Hatchways

Hatches

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Surveyor to Lloyd's Register of British and Foreign Shipping.

The Amount of Entry Fee£

Special£

Certificate (if required)£

(Travelling Expenses, if any, £)

Committee's Minute

Character assigned

4th November,

1879

IRON 488 - 0387

[The Surveyors are requested not to write on or below the space for Committee's Minute.]

[4,000—25/78.]



F. A. Lamer Wishart



© 2019

Lloyd's Register
Foundation