

* 25022

Report of Survey for Repairs of Engines and Boilers.

(Rec'd 19th 11 79)

No. _____
No. in Reg. Book. _____ Survey held at London Date, first Survey and Last Survey 17th Nov 1879
295 on the S.S. Benarty Master _____

Built at Glasgow When built 1876
Tons 1119 Owners W. Thomson & Co Port belonging to Leith
1724 Classified Lloyds reg. 11. 76
Years assigned. 00/1 Character in Register Book. 1

Diameter of Cylinder 36 1/2
Length of Stroke 39 Engines made at Glasgow When made 1876
Pressure of Steam 60
Registered Horse Power 190 By whom made Barclay Curle & Co


Particulars of Repairs and Examination at Annual Survey.
Vessel placed in dry dock and propeller &
sea connections examined propeller found barely
1/8 of an inch down, sea cocks & connections found sound
Bilge & sea suction arrangements found in accordance
with the Rule. In my opinion this vessel should
remain as classed as far as machinery is concerned

(Condition of Engines and Boilers, and subsequent Repairs and Examinations, to be clearly stated.)

The Amount of Fee ... £ : : received by me, }
Certificate (if required) ... £ : : 187 }
(Travelling Expenses, if any, £)

Committee's Minute _____ 18

James J. Melton
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register
Foundation
R00489-0004