

## ANNUAL SURVEYS.

25032

No. 38655 Survey held at London Date, first Survey 13 Nov 1879 Last Survey 14 Nov 1879  
 No. in on the Sew St Erasmus Wilson Master S. Bond  
 Reg. Book. 831 Tonnage 497 Built at Hartlepool When built 1876 3ms  
 By whom built Mithey Owners S. Clarke & Co  
 Port belonging to London Destined Voyage Shields - Coasting  
 If Surveyed Afloat or in Dry Dock Fletcher's Dry Dock

Last Survey, No. 22495 Port of Irish

Classed

Years assigned.

Character in Register Book.

90A1

1.79

Present Condition of the  
Decks

Good

Freenails Rivets

Good

Waterways

do

Breasthooks and Stemson

do

Comings

do

Transoms, Pointers, and Crutches

do

Upper Deck Beams &amp; Fastenings

do

Timbers of the Frame at the Openings

do

Lower Deck Beams &amp; Fastenings

do

Ditto ditto at other places

do

Planksheers

do

Keelsons

do

Sheerstrakes

do

Clamps and Shelves

do

Topsides

do

Ceiling

do

Wales

do

Rudder

do

Plank (Bottom) and Counter

do

Copper or Y.M. Cement When put on 76

Caulking of

Bottom, Deck, &amp; Waterways

Good

Windlass and Capstan

Good

Pumps

do

Boats

do

Masts, Yards, &amp;c.

do

Condition, how ascertained

From deck

Sails

Good

Anchors, No. of 3B. 18. 2K

Cables

Good

Hawsers and Warps

do

Standing and Running Rigging

do

Engine Room Skylights

do

Coal Bunker, Openings, Lids, &amp;c.

Good

Scuppers

do

Cargo and Main Hatchways

do

Hatches

do

General Observations, Opinion as to Class, &amp;c.

Vessel placed in dry dock - her bottom scraped and painted - Rudder partly broken - Some ceiling planks in hold renewed.

She is now in a good and efficient condition and is eligible in my opinion to remain as classed

Committee's Minute

21st November

1879.

Character assigned

90A1

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18

No. Survey held at London Date, first Survey 19 Sept 79 Last Survey 19 Sept 1879  
 No. in on the S. Eastminster Master W. Mossey  
 Reg. Book. 831 Tonnage 1145 Built at Port Glasgow When built 1876 6ms  
 By whom built Reid Owners Berryman & Turnbull  
 Port belonging to London Destined Voyage Australia  
 If Surveyed Afloat or in Dry Dock Limehouse Dry Dock

Last Survey, No. 21936 Port of Irish

Classed

Years assigned.

Character in Register Book.

100A1

10.78

Present Condition of the  
Decks

Good

Freenails Rivets

Good

Waterways

do

Breasthooks and Stemson

do

Comings

do

Transoms, Pointers, and Crutches

do

Upper Deck Beams &amp; Fastenings

do

Timbers of the Frame at the Openings

do

Lower Deck Beams &amp; Fastenings

do

Ditto ditto at other places

do

Planksheers

do

Keelsons

do

Sheerstrakes

do

Clamps and Shelves

do

Topsides

do

Ceiling

do

Wales

do

Rudder

do

Plank (Bottom) and Counter

do

Copper or Y.M. Cement When put on 76

Caulking of

Bottom, Deck, &amp; Waterways

Good

Windlass and Capstan

Good

Pumps

do

Boats

do

Masts, Yards, &amp;c.

do

Condition, how ascertained

From deck

Sails

Good

Anchors, No. of 3B. 18. 2K

Cables

Good

Hawsers and Warps

do

Standing and Running Rigging

do

Engine Room Skylights

do

Coal Bunkers, Openings, Lids, &amp;c.

Scuppers

do

Cargo and Main Hatchways

do

Hatches

do

General Observations, Opinion as to Class, &amp;c.

Vessel placed in dry dock and her bottom cleaned and painted. She is now in a good and efficient condition and is eligible in my opinion to remain as classed

Committee's Minute

21st November

1879.

Character assigned

100A1

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18