

ANNUAL SURVEYS. 25054

(Received at London Office, 18.11.79)

38653 Survey held at London Date, first Survey 3 Nov Last Survey 3 Nov 1879
 on the S.S. "Trent" Master A. Willoughby
 Tonnage 1140 Built at Glasgow When built 1840 - 9 mo.
 By whom built Lon. & Glas. & S. S. B. Co. Owners Mercantile Str. Sh. Co. (Lim.)
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Commercial Dry Dock

Last Survey, No. 21683 Port of Iron

Classed

Years assigned.

Character in Register Book.

80A1

S.S. Hul. N° 2-78

8-78

Present Condition of the
 Decks Good
 Waterways _____
 Comings _____
 Upper Deck Beams & Fastenings _____
 Lower Deck Beams & Fastenings _____
 Planksheers _____
 Sheerstrakes _____
 Topsides _____
 Wales _____
 Plank (Bottom) and Counter _____
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good
 General Observations, Opinion as to Class, &c. Rudder pintles bushed; Bottom cleaned and recoated. Two pillars in after hold straightened.

Windlass and Capstan Good
 Pumps _____
 Boats 4 h.
 Masts, Yards, &c. _____
 Condition, how ascertained from deck
 Sails Well found
 Anchors, No. of 3 B. 15. 2 K.
 Cables Complete
 Hawseers and Warps Good & sufficient
 Standing and Running Rigging Good

Committee's Minute

21st November, 1879.

Character assigned

80A1 TRW

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) _____ Paid _____ 18 _____

No. _____ Survey held at London Date, first Survey 22 Oct Last Survey 5 Nov 1879
 on the Bk. "Lady Douglas" Master Alex. Stephens
 Reg. Book. 67 Tonnage 594 Built at Greenock When built 1856
 By whom built Scott Owners Taylor, Bethell & Roberts
 Port belonging to London Destined Voyage Swan River
 If Surveyed Afloat or in Dry Dock Ruggie Dry Dock

Last Survey, No. 2228 Port of Iron

Classed

Years assigned.

Character in Register Book.

*A1

S.S. Lon N° 1-77

11-78

S.S. No. 3-72

Present Condition of the
 Decks Good
 Waterways _____
 Comings _____
 Upper Deck Beams & Fastenings _____
 Lower Deck Beams & Fastenings _____
 Planksheers _____
 Sheerstrakes _____
 Topsides _____
 Wales _____
 Plank (Bottom) and Counter _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers Good
 General Observations, Opinion as to Class, &c. The frames & plating at extreme after end of lower hold chipped and scraped and repainted. - Rudder pintles rebushed; and Bottom cleaned and recoated. This vessel is now in good condition and eligible in my opinion to remain as at present classed.

Windlass and Capstan Good
 Pumps _____
 Boats _____
 Masts, Yards, &c. _____
 Condition, how ascertained from deck & engine
 Sails Well found
 Anchors, No. of 3 B. 15. 2 K.
 Cables Complete
 Hawseers and Warps Good & sufficient
 Standing and Running Rigging Good

Committee's Minute

21st November, 1879.

Character assigned

80A1 TRW

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) _____ Paid _____ 18 _____