

S.S. "Colina"
Report of Survey for Repairs of Engines and Boilers.

No. *4998* Survey held at *Bowling & Glasgow* Date, first Survey *Nov 12 2* Last Survey *Dec 3 1849*
 Reg. Book. *833* on the *S.S. "City of Gloucester"* Master *N. Mackay*
 Name changed to *"Colina"* When built *1846-11*
 Built at *Montrose*
 Tons *134* Owners *J. E. Kerr & Co.* Port belonging to *Glasgow* Classified *90-A1*
Lloyd's M.C. 1249 Years assigned *2 1/2* Character in Register Book.
 YEAR.

Diameter of Cylinders *20" x 34"* Engines made at *Glasgow* When made *1844*
 Length of Stroke *24"* By whom made *Kemp & Home*
 Pressure of Steam *70 lbs*
 Registered Horse Power *55*

Particulars of Repairs and Examination *Engine opened up and all the working parts overhauled and examined Pumps, pipes & Bores examined Sea cocks, valves, Propeller & Steam tube examined on ship*

Boilers examined throughout, the Lops of the Combustion Chambers which had been brought down by want of water have now been renewed, and on the completion of the Repairs an hydraulic pressure was applied, of 100 lbs Two new Direct Spring loaded Safety Valves fitted, in the place of Lever & Weight and tested under steam to 40 lbs

The above Repairs have been satisfactorily completed by Messrs Hutson & Corbett and the Engines & Boilers are now in good working condition and eligible in my opinion to remain as classed and to be noted in the Register Book Lloyd's M.C. 1249

Owners wish to have Certificate

James Morrison
12/10/49

The Amount of Fee ... £ *4 : 4* : received by me
 Certificate (if required) ... £ : :
 Selling Expenses, if any, £ *1 : 1 : 0*

James Morrison
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Clyde District

Lloyd's Register
 Foundation

The machinery of this vessel has
been repaired. It is submitted
that she is eligible to
have a new machinery
certificate granted
and Lloyd's No. 79
referred
Mullins
8/12/79



© 2019

Lloyd's Register
Foundation