

REPORT of SURVEY for REPAIRS, &c.

No. 3868

(Revised 2nd, 12, 79.)

No. in
Reg. Book.Survey held at *London*Date, first Survey *22nd Oct* Last Survey *24th Oct*

1879.

167 on the

S. S. "Yeriot"

Master

W. Nesbitt

YEAR.

MONTH.

TONNAGE under Tonnage Deck *1886*

Ditto of Spar Deck, or Avoing Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

Crew Space, as per Rule

Register Tonnage, out on Beam

Engine Room

Reg. Tons as St mer, cut on Bm.

*1886**1946**1262*Built at *Sunderland*

When built

*1871**6th*Owners *C. M. Norwood & Co.*Port belonging to *London*

Residence

By whom built *Laing*Destined Voyage *Bombay*If Surveyed Afloat or in Dry Dock *on Pontoon, Victoria Dock.*

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Classed

*100 A1*Last Survey, No. *22340*Port *London**11.78**S. S. Lon. Nos - 76*

REPAIRS, OR EXAMINATION AS PER RULE

*Slight Repairs to Rudder. - Bottom cleaned & repainted. -
Surveyed with part outward cargo in fore-hold. -*

It was duly pointed out to the captain that a 3rd Bower anchor should be supplied for completion of equipment. - The captain promised to give notice, when receiving the anchor on board, which however has not been done & the vessel has now left this port. -

Present Condition of the

Deck

Water

Comin

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksh

Sheerst.

Topsie

Wales

Plank (bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Good

Treenails

Rivets

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper

Caulking of

Bottom, Deck, & Waterways

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

Hatches

Hatches

Hatches

Hatches

Hatches

Hatches

Hatches

Hatches

Hatches

Hatches

Hatches

Hatches

Hatches

Hatches

Good

Windlass and Capstan

Pumps

Boats *6 in number*

Masts, Yards, &c.

Condition, how ascertained *from deck & inquiry*

Sails

Anchors No. of *2 B. 1 St. 2 H*Cables *part seen*

Hawsers and Warps

Standing & Running Rigging

Cargo and Main Hatchways

Hatches

Hatches

Hatches

Hatches

Hatches

Hatches

Hatches

Hatches

Hatches

Hatches

Hatches

Hatches

Hatches

Hatches

Hatches

Hatches

Hatches

Hatches

The Amount of Entry Fee£

Special£

Certificate (if required)£

(Travelling Expenses, if any, £)

Committee's Minute

2nd December,

1879.

9th December,

79.

Character assigned

*100 A1**3/12/79*

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register
Foundation

RON489-0189