

# REPORT of SURVEY for REPAIRS, &c.

No. 27.

No. in Survey held at Reg. Book.

Malta

Date, first Survey

Nov. 19

Last Survey

Nov. 19

1879.

36 on the Iron Screw Steamer "Vanessa"

Master

J. W. Dobbin

Official Number  
TONNAGE under Tonnage Deck  
Ditto of Spar Deck, or Awning Deck  
Ditto of Poop  
Ditto of Raised Qr. Dk.  
Ditto of Houses on Deck  
Ditto of Forecastle  
Gross Tonnage  
Crew Space, as per Rule  
Register Tonnage, cut on Beam  
Engine Room  
Reg. Tons as S<sup>t</sup> mer, cut on Bm.

Built at

Newcastle

When built

1872

YEAR.  
MONTH.

2.

Owners

J. Fenwick & Son

Port belonging to

London

Residence

57. Gracechurch St. London

By whom built

Palmer

Destined Voyage

Alexandria

If Surveyed Afloat or in Dry Dock

On Hydraulic Dock Pontoon

Length of Poop

ft.

Ditto, Forecastle

39.

ft.

Ditto, Raised Quarter Deck

80.

ft.

Years assigned.

Character in Register Book.

Last Survey, No. 1

46 Cardiff

Port

London

Classed

+

100 A1

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

S.S. No. 1-76

8.77

This vessel during her passage to Malta, when off the coast of Algiers, struck heavily on some floating or half sunken wreck on the Port side, which swept right into the Screw, carrying away blades of the same. Her Hull was carefully examined, and the marks of the timbers of the wreck, were found cut into the paint on bottom, like so many teeth marks. The bolts of wreck had also scored right along the side, rubbing the plates bright, but beyond all this superficial damage, none other was found. The vessel was scraped and coated.

Herewith I beg to hand you, report on Machinery by Mr. Finchcliffe

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper (or T.M.)

Paint When put on new

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Nothing has happened to this vessel to vitiate her Class in our Books.

The Amount of Entry Fee ... £ : : received by me,

Special ... £ 1 : 1 : "

Dec. 1 - 1879.

Certificate (if required)

to be sent as per margin...

(Travelling Expenses, if any, £ )

Committee's Minute

21b. December,

1879.

Character assigned

100 A1

DBW 8.77 as above

Whitton

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

IRON489-0192