

# ANNUAL SURVEYS.

No. 20 Survey held at Sourabaya Date, first Survey \_\_\_\_\_ Last Survey 29 October 1879  
 No. in on the British Ship Aberaman Master B. Davies  
 Reg. Book. 27 Tonnage 1090 Built at Stockton When built July 1875  
 By whom built Richardson Owners G. H. Capper & Co  
 Port belonging to Cardiff Destined Voyage Channel for order  
 If Surveyed Afloat or in Dry Dock Afloat.

Last Survey, No. 23220 Port of Swan 3/79 Classed \_\_\_\_\_ Years assigned. \_\_\_\_\_ Character in Register Book. 100 A1  
 Present Condition of the \_\_\_\_\_  
 Decks Good Treenails \_\_\_\_\_  
 Waterways good Breasthooks and Stemson \_\_\_\_\_  
 Mings good Transoms, Pointers, and Crutches good  
 Upper Deck Beams & Fastenings good Timbers of the Frame at the Openings good  
 Lower Deck Beams & Fastenings good Ditto ditto at other places \_\_\_\_\_  
 Keelsons good  
 Clamps and Shelves \_\_\_\_\_  
 Ceiling good  
 Rudder good  
 Copper or Y.M. \_\_\_\_\_ When put on \_\_\_\_\_  
 Caulking of \_\_\_\_\_  
 Bottom, Deck, & Waterways good  
 Windlass and Capstan Good  
 Pumps good  
 Boats good  
 Masts, Yards, &c. good  
 Condition, how ascertained by Enquiry & Exam.  
 Sails good  
 Anchors, No. of 3 B 1 2 1 2 1 2  
 Cables good  
 Hawcsers and Warps good  
 Standing and Running Rigging good  
 Fine Room Skylights \_\_\_\_\_ Coal Bunker, Openings, Lids, &c. \_\_\_\_\_ Scuppers good Cargo and Main Hatchways good Hatches good

General Observations, Opinion as to Class, &c. This Vessel is at the present time in a good and efficient state of repair, fit for the conveyance of dry and perishable goods to and from all parts of the world. And in our opinion merits the favorable consideration of the Committee to be continued in her present class. 100 A1  
 Committee's Minute \_\_\_\_\_ 23rd December, 1879.  
 Character assigned 100 A1  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_

Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18 \_\_\_\_\_  
 No. in on the \_\_\_\_\_ Master \_\_\_\_\_  
 Reg. Book. \_\_\_\_\_ Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_ Years assigned. \_\_\_\_\_ Character in Register Book. \_\_\_\_\_  
 Present Condition of the \_\_\_\_\_  
 Decks \_\_\_\_\_ Treenails \_\_\_\_\_  
 Waterways \_\_\_\_\_ Breasthooks and Stemson \_\_\_\_\_  
 Mings \_\_\_\_\_ Transoms, Pointers, and Crutches \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_ Timbers of the Frame at the Openings \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_ Ditto ditto at other places \_\_\_\_\_  
 Keelsons \_\_\_\_\_  
 Clamps and Shelves \_\_\_\_\_  
 Ceiling \_\_\_\_\_  
 Rudder \_\_\_\_\_  
 Copper or Y.M. \_\_\_\_\_ When put on \_\_\_\_\_  
 Caulking of \_\_\_\_\_  
 Bottom, Deck, & Waterways \_\_\_\_\_  
 Windlass and Capstan \_\_\_\_\_  
 Pumps \_\_\_\_\_  
 Boats \_\_\_\_\_  
 Masts, Yards, &c. \_\_\_\_\_  
 Condition, how ascertained \_\_\_\_\_  
 Sails \_\_\_\_\_  
 Anchors, No. of \_\_\_\_\_  
 Cables \_\_\_\_\_  
 Hawcsers and Warps \_\_\_\_\_  
 Standing and Running Rigging \_\_\_\_\_  
 Fine Room Skylights \_\_\_\_\_ Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_ Scuppers \_\_\_\_\_ Cargo and Main Hatchways \_\_\_\_\_ Hatches \_\_\_\_\_

General Observations, Opinion as to Class, &c. \_\_\_\_\_  
 Committee's Minute \_\_\_\_\_ 18 \_\_\_\_\_  
 Character assigned \_\_\_\_\_  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_