

ANNUAL SURVEYS.

25786

No. 38/38 Survey held at London Date, first Survey 12th Dec^r Last Survey 13th Dec^r 1879
 No. in on the S. S. "Balachava" Master J. Atkins.
 g. Book. 16 Tonnage 221 Built at Glasgow When built 1876 - 6 mo
 By whom built Kippen Owners R. Thomson & Co.
 Port belonging to London Destined Voyage Continent
 If Surveyed Afloat or in Dry Dock Bull Head Dry Dock.

Last Survey, No. 24210 Port of Spain
 Present Condition of the
 keels Good Treenails Rivets Good
 Waterways " Breasthooks and Stems "
 Timings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Sides " Ceiling "
 Plates " Rudder "
 (Bottom) and Counter " Copper or Y.M. Cement When put on 1876
 Caulking of Bottom, Deck, & Waterways Good
 Windlass and Capstan Good
 Pumps "
 Boats "
 Masts, Yards, &c. "
 Condition, how ascertained Deck &c.
 Sails Good
 Anchors, No. of 3 B - 1 B - 2 B
 Cables Good
 Hawesers and Warps do.
 Standing and Running Rigging do.
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom examined, cleaned and coated with composition.

This Vessel is now in good and efficient condition, and eligible to remain as Classed.

Committee's Minute 23rd December, 1879.
 Character assigned 100A OTBW
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 38 Survey held at London Date, first Survey 18th Dec^r Last Survey 18th Dec^r 1879
 No. in on the S. S. "Solis" Master J. de'Almeida
 g. Book. 826 Tonnage 531 Built at Glasgow When built 1874 - 8 mo
 By whom built Stephen Owners J. Roca & Co
 Port belonging to Barcelona Destined Voyage Spain
 If Surveyed Afloat or in Dry Dock Afloat Fresh Wharf

Last Survey, No. 1933 Port of Spain
 Present Condition of the
 keels Good Treenails Rivets Good
 Waterways " Breasthooks and Stems "
 Timings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Sides " Ceiling "
 Plates " Rudder "
 (Bottom) and Counter not seen Copper or Y.M. Cement When put on 1877
 Caulking of Bottom, Deck, & Waterways Good
 Windlass and Capstan Good
 Pumps "
 Boats "
 Masts, Yards, &c. "
 Condition, how ascertained Deck &c.
 Sails Good
 Anchors, No. of 3 B - 1 B - 2 B
 Cables Good
 Hawesers and Warps "
 Standing and Running Rigging "
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Surveyed afloat and where seen in good condition, and eligible to remain as Classed.

Committee's Minute 23rd December, 1879.
 Character assigned 100A OTBW
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18