

ANNUAL SURVEYS. 25223

No. 14621 Survey held at Newcastle Date, first Survey and Last Survey 11th Decr 1879
 No. in on the Am S.S. Lutetia Master - Abell
 Reg. Book 894 Tonnage 874 Built at San deland When built 1877 - 12 mo
 By whom built Thompson Owners Bell & Symonds
 Port belonging to Newcastle Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Palmer's dock
 Last Survey, No. 24659 Port of Newcastle

Present Condition of the
 Decks good Rivets: good Loose m.b. 1, 78. 9.79
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers do Keelsons do
 Sheerstrakes do Clamps and Shelves do
 Topsides do Ceiling do
 Wales do Rudder do
 Plank (Bottom) and Counter do Caulking of do
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. The bottom of this vessel has now been scraped and painted, and a plate on Port side of the Forecastle has been renewed, the former one having been damaged. The vessel appears to be in good and efficient condition, and eligible, in my opinion, to remain as classed.

Committee's Minute 19th December, 1879

Character assigned GOA JBW

R. J. Reed.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 14631 Survey held at S. Shields Date, first Survey and Last Survey 10th Decr 1879
 No. in on the Bⁿ Broomshield Master R. Young
 Reg. Book 807 Tonnage 364 Built at Newcastle When built 1874 - 2 mo
 By whom built Cole Owners Jully Bros & Co
 Port belonging to Newcastle Destined Voyage ✓
 If Surveyed Afloat or in Dry Dock Patent Ship
 Last Survey, No. 23164 Port of Newcastle

Present Condition of the
 Decks Good Rivets: Good S.S. Nuc No 1-78. 3.79
 Waterways D Breasthooks and Stemson D
 Comings D Transoms, Pointers, and Crutches D
 Upper Deck Beams & Fastenings D Timbers of the Frame at the Openings D
 Lower Deck Beams & Fastenings D Ditto ditto at other places D
 Planksheers D Keelsons D
 Sheerstrakes D Clamps and Shelves D
 Topsides D Ceiling D
 Wales D Rudder D
 Plank (Bottom) and Counter D Copper or Y.M. Paint When put on new
 Engine Room Skylights - Coal Bunkers, Openings, Lids, &c. - Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. The Bottom sighted, cleaned and repainted. This vessel is now in good and efficient condition, and in my opinion eligible to remain as classed.

Committee's Minute 19th December, 1879

Character assigned GOA JBW

W. M. Overly.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18