

14/79

ANNUAL SURVEYS.

Recd 5-4-79

No. _____ Survey held at London Date, first Survey March 24 Last Survey March 28 1879

No. in on the SS Palmyra Master _____

Reg. Book. 58 Tonnage 707 Built at Newcastle When built 1866 LM

By whom built Palmer Owners Lon St Ship Co.

Port belonging to London Destined Voyage _____

Surveyed Afloat or in Dry Dock Penton Victoria Dock

Survey, No. 22120 Port of Lron

Years assigned. _____ Character in Register Book. _____
Classed 90A 10.78
SS Lon M277

is
recor
faron
com

Condition of the	<u>Good</u>	Treenails <u>Pivets</u>	<u>Good</u>	Windlass and Capstan	
	"	Breasthooks and Stems	"	Pumps	
	"	Transoms, Pointers, and Crutches	"	Boats	
	"	Timbers of the Frame at the Openings	"	Masts, Yards, &c.	<u>Good &</u>
Fastenings	"	Ditto ditto at other places	"	Condition, how ascertained	<u>Sufficient</u>
Fastenings	"	Keelsons	"	Sails	<u>where</u>
	"	Clamps and Shelves	"	Anchors, No. of <u>3 Iron, 29 lead</u>	<u>they</u>
	"	Ceiling	"	Cables	<u>could</u>
	"	Rudder	"	Hawsers and Warps	<u>be seen</u>
	"	Copper or Y.M. <u>Coated</u>	When put on <u>Now</u>	Standing and Running Rigging	
Plank (_____ Counter	"	Caulking of			
Engine Room Skylights <u>Good</u>		Bottom, Deck, & Waterways	<u>Good</u>		
Coal Bunker, Openings, Lids, &c.	<u>Good</u>	Scuppers	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>
General Observations, Opinion as to Class, &c.				Hatches	<u>Good</u>

She is now in good condition and entitled to remain as classed, the owners could not conveniently carry out the SSM3 at this time

Letter to owner 28/4/79

Character assigned Deficiency 22 April 1879 18
Longest S. Jones Deficiency Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) _____ Paid _____ 18 _____

IRON 489-0552