

# ANNUAL SURVEYS.

25384

No. 38,846. Survey held at London Date, first Survey 12 Jan<sup>y</sup> Last Survey 12 Jan<sup>y</sup> 1880  
 No. in on the Bagui Quathlamba Master Smith  
 Reg. Book. 7 Tonnage 467 Built at Sherdeen When built 1879 - 2 m  
 By whom built Hall & Co Owners Reune & Son  
 Port belonging to Sherdeen Destined Voyage Natal  
 If Surveyed Afloat or in Dry Dock Ratchiff dry dock

Last Survey, No. 22847 Port of Don Classed 100 A1  
 Years assigned. 3.79 Character in Register Book.

Present Condition of the Decks Good Treeails Points Good  
 Waterways d<sup>c</sup> Breasthooks and Stenson d<sup>c</sup>  
 Comings d<sup>c</sup> Transoms, Pointers, and Crutches d<sup>c</sup>  
 Upper Deck Beams & Fastenings d<sup>c</sup> Timbers of the Frame at the Openings d<sup>c</sup>  
 Lower Deck Beams & Fastenings d<sup>c</sup> Ditto ditto at other places d<sup>c</sup>  
 Planksheers d<sup>c</sup> Keelsons d<sup>c</sup>  
 Sheerstrakes d<sup>c</sup> Clamps and Shelves d<sup>c</sup>  
 Topsides d<sup>c</sup> Ceiling d<sup>c</sup>  
 Vales d<sup>c</sup> Rudder d<sup>c</sup>  
 (Bottom) and Counter d<sup>c</sup> Copper or Y.M. ✓ When put on ✓  
 Caulking of Bottom, Deck, & Waterways d<sup>c</sup>  
 Engine Room Skylights d<sup>c</sup> Coal Bunker, Openings, Lids, &c. d<sup>c</sup> Scuppers d<sup>c</sup> Cargo and Main Hatchways d<sup>c</sup> Hatches d<sup>c</sup>  
 General Observations, Opinion as to Class, &c. The bottom cleaned and recoated. This vessel appears in good condition and eligible to remain as classed

Committee's Minute Friday, January, 30th 1880  
 Character assigned 100 A1  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) ✓ Paid 18

No. 38,847 Survey held at London Date, first Survey 13 Jan<sup>y</sup> Last Survey 13 Jan<sup>y</sup> 1880  
 No. in on the S. S. Gallina Master Maen  
 Reg. Book. 58 Tonnage 1210 Built at Lunderland When built 1878 - 10 m  
 By whom built Murray Owners Potens & Senior  
 Port belonging to London Destined Voyage not known  
 If Surveyed Afloat or in Dry Dock Bridge dry dock

Last Survey, No. 24842 Port of Don Classed 100 A1  
 Years assigned. 9.79 Character in Register Book.

Present Condition of the Decks Good Treeails Points Good  
 Waterways d<sup>c</sup> Breasthooks and Stenson d<sup>c</sup>  
 Comings d<sup>c</sup> Transoms, Pointers, and Crutches d<sup>c</sup>  
 Upper Deck Beams & Fastenings d<sup>c</sup> Timbers of the Frame at the Openings d<sup>c</sup>  
 Lower Deck Beams & Fastenings d<sup>c</sup> Ditto ditto at other places d<sup>c</sup>  
 Planksheers d<sup>c</sup> Keelsons d<sup>c</sup>  
 Sheerstrakes d<sup>c</sup> Clamps and Shelves d<sup>c</sup>  
 Topsides d<sup>c</sup> Ceiling d<sup>c</sup>  
 Vales d<sup>c</sup> Rudder d<sup>c</sup>  
 (Bottom) and Counter d<sup>c</sup> Copper or Y.M. ✓ When put on ✓  
 Caulking of Bottom, Deck, & Waterways d<sup>c</sup>  
 Engine Room Skylights d<sup>c</sup> Coal Bunkers, Openings, Lids, &c. d<sup>c</sup> Scuppers d<sup>c</sup> Cargo and Main Hatchways d<sup>c</sup> Hatches d<sup>c</sup>  
 General Observations, Opinion as to Class, &c. The bottom cleaned and recoated. This vessel appears in good condition and eligible to remain as classed.

Committee's Minute Friday, January, 30th 1880  
 Character assigned 100 A1  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) ✓ Paid 18