

ANNUAL SURVEYS.

2570680

(Received at London Office, 10/2/80)

No. in Reg. Book 28891 Survey held at London Date, first Survey July 30 Last Survey July 30 1880
 on the SS Blan Randa Master ✓
 Tonnage 1357 Built at Dumbarton When built 1878 12M
 By whom built Mc Millan Owners Cayen Irvine & Co
 Port belonging to Glasgow Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Blackwall Pt Dry Dock

Last Survey, No. 23452 Port of Iron Classed 100A-779 Years assigned. Character in Register Book.

Present Condition of the Decks	<u>Good</u>	Treenails	<u>Pivets</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	"	Breasthooks and Stemson		"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches		"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings		"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places		"	Condition, how ascertained	<u>Exam & H</u>
Planksheers	"	Keelsons		"	Sails	<u>Good</u>
Sheerstrakes	"	Clamps and Shelves		"	Anchors, No. of <u>3</u> Nos. <u>H & K</u> & <u>Kedgs</u>	
Topsides	"	Ceiling		"	Cables <u>Part on H</u>	<u>Good</u>
Wales	"	Rudder		"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Coated</u> When put on <u>one</u>		"	Standing and Running Rigging	"
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways		<u>Good</u>	Scuppers <u>Good</u> Cargo and Main Hatchways <u>Good</u> Hatches	"
General Observations, Opinion as to Class, &c.	<u>Bottom &c coated.</u>					

She is now in good condition and eligible to remain as classed.

Committee's Minute Friday, February, 13th 1880 Surveyor Senhouse Martindale
 Character assigned 100 TBSW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) ✓ Paid 18

Survey held at London Date, first Survey July 17 Last Survey July 31 1880
 on the S British Sceptre Master H Richard
 Tonnage 1436 Built at Liverpool When built 1868 4M
 By whom built Royden Owners British Ship Owners Co
 Port belonging to Liverpool Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock Blackwall Pt Dry Dock

Last Survey, No. 21924 Port of Iron Classed 100A 10.78 Years assigned. Character in Register Book.

Present Condition of the Decks	<u>Good</u>	Treenails	<u>Pivets</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	"	Breasthooks and Stemson		"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches		"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings		"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places		"	Condition, how ascertained	<u>Exam & H</u>
Planksheers	"	Keelsons		"	Sails	<u>Good</u>
Sheerstrakes	"	Clamps and Shelves		"	Anchors, No. of <u>3</u> Nos. <u>H & K</u> & <u>Kedgs</u>	
Topsides	"	Ceiling		"	Cables <u>Part on H</u>	<u>Good</u>
Wales	"	Rudder		"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Coated</u> When put on <u>none</u>		"	Standing and Running Rigging	"
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways		<u>Good</u>	Scuppers <u>Good</u> Cargo and Main Hatchways <u>Good</u> Hatches	"
General Observations, Opinion as to Class, &c.	<u>Bottom &c coated.</u>					

She is now in good condition and eligible to remain as classed.

Committee's Minute Friday, February, 13th 1880 Surveyor Senhouse Martindale
 Character assigned 100 TBSW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) ✓ Paid 18

