

ANNUAL SURVEYS.

No. 14425 Survey held at Newcastle Date, first Survey 9th Feb'y Last Survey 9th Feb'y 1880
 No. in Reg. Book. 122 on the Iron S.S. "Telesilla" Master W. A. Kirkaldy
 Tonnage 1233 Built at Hartlepool When built 1877-1 mo.
 By whom built W. G. Greenwell Owners T. G. Greenwell
 Port belonging to London Destined Voyage West coast of Africa
 If Surveyed Afloat or in Dry Dock In Palmers' Dry Dock

Last Survey, No. 23912 Port of Iron Classed 90A-1
 Present Condition of the
 Decks good Treenails rivets good
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, ~~Pointers~~, and Crutches do
 Upper Deck Beams & Fastenings do ~~Timbers~~ of the Frame at the Openings do
 Lower Deck Beams & Fastenings do ~~Ditto~~ ditto at other places do
 Planksheers do Keelsons do
 Sheerstrakes do Clamps and Shelves do
 Topsides do Ceiling do
 Rudder do
~~Copper or Y.M.~~ When put on
 Caulking of Bottom, Deck, & Waterways good
 Windlass and Capstan good
 Pumps do
 Boats do
 Masts, Yards, &c. do
 Condition, how ascertained ex^d from the deck
 Sails good
 Anchors, No. of 3 B. 1 S. 2 K.
 Cables good
 Hawesers and Warps do
 Standing and Running Rigging do
 Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. The bottom has been cleaned and coated.

A 1st kedge anchor has now been supplied - weight ex. stock 5-8-3 - tension 8-10-0-0
 D. Perry Superintendent Old Hill near Dudley, 22nd Dec^r/79.
 As the machine at which this anchor was tested is not recognized by the Committee, the Owner has been communicated with and states that on the return of the steamer to the Type the anchor will be changed. In other respects the vessel appears to be in good and efficient condition & eligible to remain as classed.

Committee's Minute Friday, February, 27th 1880
 Character assigned 90A-1 DTBW
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in Reg. Book. on the Master
 Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed
 Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Rudder
 Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Windlass and Capstan
 Pumps
 Boats
 Masts, Yards, &c.
 Condition, how ascertained
 Sails
 Anchors, No. of
 Cables
 Hawesers and Warps
 Standing and Running Rigging
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

