

ANNUAL SURVEYS.

25826

No. 14404 Survey held at S. Shields Date, first Survey Feb 6th Last Survey Feb 6th 1880
 No. in Reg. Book. 283 on the Iron S. S. "Vindomora" Master R. Meadows
 Tonnage 692 Built at Sunderland When built 1873 7 mo
 By whom built Thompson Owners Bell & Symonds
 Port belonging to London Destined Voyage /
 Surveyed Afloat or in Dry Dock Wilson & Blain Dock

Last Survey, No. 25246 Port of Iron
 Present Condition of the
 Decks Good Treenails Piwets Good
 Waterways D^c Breasthooks and Stemson D^c
 Comings D^c Transoms, Pointers, and Crutches D^c
 Upper Deck Beams & Fastenings D^c Timbers of the Frame at the Openings D^c
 Lower Deck Beams & Fastenings D^c Ditto ditto at other places D^c
 Planksheers D^c Keelsons D^c
 Sheerstrakes D^c Clamps and Shelves D^c
 Topsides D^c Ceiling D^c
 Wales D^c Rudder D^c
 Plank (Bottom) and Counter D^c Copper or Y.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Windlass and Capstan Good
 Pumps D^c
 Boats D^c
 Masts, Yards, &c. D^c
 Condition, how ascertained By examination
 Sails /
 Anchors, No. of 3
 Cables Complete
 Hawcsers and Warps /
 Standing and Running Rigging Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom sighted, cleaned and repainted.

Committee's Minute Tuesday, February, 17th 1880.
 Character assigned GOA JRM Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) / Paid / 18

No. 1326 Survey held at South Shields Date, first Survey Feb 2nd Last Survey Feb 2nd 1880
 No. in Reg. Book. 1326 on the Iron S. S. "Coronilla" Master J. Robinson
 Tonnage 875 Built at Newcastle When built 1878 12 mo
 By whom built Syde. J. S. B. Co. Ltd Owners J. Robinson
 Port belonging to North Shields Destined Voyage /
 Surveyed Afloat or in Dry Dock Edwards Dry Dock

Last Survey, No. 23567 Port of Iron
 Present Condition of the
 Decks Good Treenails Piwets Good
 Waterways D^c Breasthooks and Stemson D^c
 Comings D^c Transoms, Pointers, and Crutches D^c
 Upper Deck Beams & Fastenings D^c Timbers of the Frame at the Openings D^c
 Lower Deck Beams & Fastenings D^c Ditto ditto at other places D^c
 Planksheers D^c Keelsons D^c
 Sheerstrakes D^c Clamps and Shelves D^c
 Topsides D^c Ceiling D^c
 Wales D^c Rudder D^c
 Plank (Bottom) and Counter D^c Copper or Y.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Windlass and Capstan Good
 Pumps D^c
 Boats D^c
 Masts, Yards, &c. D^c
 Condition, how ascertained By examination
 Sails /
 Anchors, No. of 3
 Cables Complete
 Hawcsers and Warps /
 Standing and Running Rigging Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. The Bottom sighted, cleaned and repainted.

Committee's Minute Tuesday, February, 17th 1880.
 Character assigned GOA JRM Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) / Paid / 18