

ANNUAL SURVEYS.

25841

8870 Survey held at London Date, first Survey Jan 8th Last Survey Jan 31st 1880
on the SS Himalaya Master Pittella
Tonnage 1008 Built at Sunderland When built 1863-11th
By whom built Pile Owners Shaw Savill & Co
Port belonging to Southampton Destined Voyage New Zealand
If Surveyed Afloat or in Dry Dock Blackwall Point Dry Dock

Last Survey, No. 22566 Port of Iron

Classed 1A Years assigned 1. 1.75 Character in Register Book.

Condition of the	<u>good</u>	Treenails	<u>Rivets</u>	<u>good</u>	<u>S. L. L. 3-69 SS Lin W 2-77</u>
Waterways	"	Breasthooks and Stemson	"	"	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Windlass and Capstan <u>good</u>
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Pumps "
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Boats "
Planksheers	"	Keelsons	"	"	Masts, Yards, &c. "
Sheerstrakes	"	Clamps and Shelves	"	"	Condition, how ascertained <u>from SK</u>
Topsides	"	Ceiling	"	"	Sails <u>good</u>
Wales	"	Rudder	"	"	Anchors, No. of <u>3 Bns. SK & Reddy</u>
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Coated</u> When put on <u>new</u>	"	"	Cables <u>Part on SK</u> <u>good</u>
Engine Room Skylights	"	Caulking of	"	"	Hawsers and Warps "
General Observations, Opinion as to Class, &c.	"	Bottom, Deck, & Waterways	<u>good</u>	"	Standing and Running Rigging "
		Coal Bunker, Openings, Lids, &c.	<u>good</u>	"	Cargo and Main Hatchways <u>good</u>
		Scuppers	<u>good</u>	"	Hatches <u>good</u>

She is now in good condition and eligible to remain as classed

Committee's Minute Friday, February, 6th 1880

Character assigned 1A

Senhouse Martindale
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18

No. 560 Survey held at London Date, first Survey Jan 12 Last Survey Jan 30th 1880

No. in Reg. Book. 560 on the SS Sestos Master Tilmouth
Tonnage 784 Built at Glasgow When built 1872 8th AM
By whom built Sen & Glas Co Owners Globe Star Ship Co
Port belonging to London Destined Voyage China
If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock

Last Survey, No. 22795 Port of Iron

Classed 100A Years assigned 2.75 Character in Register Book.
SS Lon W 1-77

Present Condition of the	<u>good</u>	Treenails	<u>Rivets</u>	<u>good</u>	<u>S. L. L. 3-69 SS Lin W 2-77</u>
Decks	"	Breasthooks and Stemson	"	"	"
Waterways	"	Transoms, Pointers, and Crutches	"	"	Windlass and Capstan <u>good</u>
Comings	"	Timbers of the Frame at the Openings	"	"	Pumps "
Upper Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Boats "
Lower Deck Beams & Fastenings	"	Keelsons	"	"	Masts, Yards, &c. "
Planksheers	"	Clamps and Shelves	"	"	Condition, how ascertained <u>from SK</u>
Sheerstrakes	"	Ceiling	"	"	Sails <u>good</u>
Topsides	"	Rudder	"	"	Anchors, No. of <u>3 Bns. SK & Reddy</u>
Wales	"	Copper or Y.M. <u>Coated</u> When put on <u>new</u>	"	"	Cables <u>Part on SK</u> <u>good</u>
Plank (Bottom) and Counter	"	Caulking of	"	"	Hawsers and Warps "
Engine Room Skylights	<u>good</u>	Bottom, Deck, & Waterways	<u>good</u>	"	Standing and Running Rigging "
General Observations, Opinion as to Class, &c.	"	Coal Bunkers, Openings, Lids, &c.	<u>good</u>	"	Cargo and Main Hatchways <u>good</u>
		Scuppers	<u>good</u>	"	Hatches "

She is now in good condition and eligible to remain as classed

Committee's Minute Friday, February, 6th 1880

Character assigned 100A

Senhouse Martindale
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18