

## ANNUAL SURVEYS.

25985

No. 39022 Survey held at London Date, first Survey 8<sup>th</sup> March Last Survey 8 March 1880  
No. in on the R<sup>e</sup> "Catalpa" Master Panton  
Reg. Book. 358 Tonnage 676 Built at Sunderland When built 1869-1  
By whom built Pile Owners Devitt & Moore  
Port belonging to London Destined Voyage Adelaide  
If Surveyed Afloat or in Dry Dock Union dry dock

Last Survey, No. 22858 Port of Iron

Present Condition of the

Decks	Good	Timbers	Pine	Good
Waterways	<u>dc</u>	Breasthooks and Stemson	<u>dc</u>	
Comings	<u>dc</u>	Transoms, Pointers, and Crutches	<u>dc</u>	
Upper Deck Beams & Fastenings	<u>dc</u>	Timbers of the Frame at the Openings	<u>dc</u>	
Lower Deck Beams & Fastenings	<u>dc</u>	Ditto ditto at other places	<u>dc</u>	
Planksheers	<u>dc</u>	Keelsons	<u>dc</u>	
Sheerstrakes	<u>dc</u>	Clamps and Shelves	<u>dc</u>	
Topsides	<u>dc</u>	Ceiling	<u>dc</u>	
Wales	<u>dc</u>	Rudder	<u>dc</u>	
Plank (Bottom) and Counter	<u>dc</u>	Copper or Y.M. <input checked="" type="checkbox"/> When put on <input checked="" type="checkbox"/>		
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways	<u>dc</u>	
Coal Bunker, Openings, Lids, &c.		Scuppers	<u>dc</u>	
General Observations, Opinion as to Class, &c.		Cargo and Main Hatchways	<u>dc</u>	

Windlass and Capstan Good  
Pumps two dc  
Boats three dc  
Masts, Yards, &c. dc  
Condition, how ascertained from deck  
Sails well found  
Anchors, No. of 20. 18 & 16  
Cables complete  
Hawsers and Warps sufficient  
Standing and Running Rigging good  
Hatches good

Classed

Years assigned.

Character in Register Book.

1. 3. 79  
P.P. 4. 2. 77.

Committee's Minute

Friday, April, 2nd 1880

Character assigned

Thos. Congdon

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18

No. 116 Survey held at London Date, first Survey 1<sup>st</sup> March Last Survey 30 March 1880  
No. in on the L. Cambrian Monarch Master Thos. Owen  
Reg. Book. 116 Tonnage 1306 Built at Louthampton When built 1876-7  
By whom built Aswalds Owners Williams & Co.  
Port belonging to Lpool Destined Voyage Sydney  
If Surveyed Afloat or in Dry Dock Princes dry dock

Last Survey, No. 20583 Port of Iron

Present Condition of the

Decks	Good	Timbers	Pine	Good
Waterways	<u>dc</u>	Breasthooks and Stemson	<u>dc</u>	
Comings	<u>dc</u>	Transoms, Pointers, and Crutches	<u>dc</u>	
Upper Deck Beams & Fastenings	<u>dc</u>	Timbers of the Frame at the Openings	<u>dc</u>	
Lower Deck Beams & Fastenings	<u>dc</u>	Ditto ditto at other places	<u>dc</u>	
Planksheers	<u>dc</u>	Keelsons	<u>dc</u>	
Sheerstrakes	<u>dc</u>	Clamps and Shelves	<u>dc</u>	
Topsides	<u>dc</u>	Ceiling	<u>dc</u>	
Wales	<u>dc</u>	Rudder	<u>dc</u>	
Plank (Bottom) and Counter	<u>dc</u>	Copper or Y.M. <input checked="" type="checkbox"/> When put on <input checked="" type="checkbox"/>		
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways	<u>dc</u>	
Coal Bunkers, Openings, Lids, &c.		Scuppers	<u>dc</u>	
General Observations, Opinion as to Class, &c.		Cargo and Main Hatchways	<u>dc</u>	

Windlass and Capstan Good  
Pumps two dc  
Boats four dc  
Masts, Yards, &c. dc  
Condition, how ascertained from deck  
Sails well found  
Anchors, No. of 20. 18 & 16  
Cables complete  
Hawsers and Warps sufficient  
Standing and Running Rigging good  
Hatches dc

Classed

Years assigned.

Character in Register Book.

100 A  
3. 78

Committee's Minute

Friday, April, 2nd 1880

Character assigned

Thos. Congdon

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18



Contalpa  
&

Barbara Kennedy



© 2019

Lloyd's Register  
Foundation