

ANNUAL SURVEYS.

25870

No. 28746 Survey held at London Date, first Survey 11th Decr. Last Survey 12th Decr. 1879.
 No. in Reg. Book. on the Ship "Yantallan Castle" Master H. Hay
 Tonnage 1057 1057 985 Built at Greenock When built 1865 3rd mo.
 By whom built Steele Owners Currie & Co.
 Port belonging to Liverpool Destined Voyage New York.
 If Surveyed Afloat or in Dry Dock West India Dredging Dock

Last Survey, No.	Port of	Classed	Years assigned.	Character in Register Book.
				<u>All</u>
Present Condition of the Decks				
Waterways	<u>do</u>	<u>Good</u>	<u>Treenails</u>	<u>Rivets</u>
Comings	<u>do</u>	<u>do</u>	<u>do</u>	<u>do</u>
Upper Deck Beams & Fastenings	<u>do</u>	<u>do</u>	<u>do</u>	<u>do</u>
Lower Deck Beams & Fastenings	<u>do</u>	<u>do</u>	<u>do</u>	<u>do</u>
Planksheers	<u>do</u>	<u>do</u>	<u>do</u>	<u>do</u>
Sheerstrakes	<u>do</u>	<u>do</u>	<u>do</u>	<u>do</u>
Topsides	<u>do</u>	<u>do</u>	<u>do</u>	<u>do</u>
Wales	<u>do</u>	<u>do</u>	<u>do</u>	<u>do</u>
Plank (Bottom) and Counter	<u>do</u>	<u>do</u>	<u>do</u>	<u>do</u>
Engine Room Skylights	<u>do</u>	<u>do</u>	<u>do</u>	<u>do</u>
Coal Bunker, Openings, Lids, &c.	<u>do</u>	<u>do</u>	<u>do</u>	<u>do</u>
Scuppers	<u>do</u>	<u>do</u>	<u>do</u>	<u>do</u>
Cargo and Main Hatchways	<u>do</u>	<u>do</u>	<u>do</u>	<u>do</u>
Hatches	<u>do</u>	<u>do</u>	<u>do</u>	<u>do</u>

Rudder pintles bushed. - Bottom cleaned & repainted. -
 Surveyed with ballast in hold, in way of main hatch. -
 Special Survey No 3 was completed in April 1878. -

She is in good condition and eligible in my opinion to remain as classed. -
 Committee's Minute 30th December, 1879.
 Character assigned TRW S.S. No 3-78 on page 48
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in Reg. Book. on the Master
 Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No.	Port of	Classed	Years assigned.	Character in Register Book.
Present Condition of the Decks				
Waterways			<u>Treenails</u>	
Comings			<u>Breasthooks and Stemson</u>	
Upper Deck Beams & Fastenings			<u>Transoms, Pointers, and Crutches</u>	
Lower Deck Beams & Fastenings			<u>Timbers of the Frame at the Openings</u>	
Planksheers			<u>Ditto ditto at other places</u>	
Sheerstrakes			<u>Keelsons</u>	
Topsides			<u>Clamps and Shelves</u>	
Wales			<u>Ceiling</u>	
Plank (Bottom) and Counter			<u>Rudder</u>	
Engine Room Skylights			<u>Copper or Y.M.</u>	<u>When put on</u>
Coal Bunkers, Openings, Lids, &c.			<u>Caulking of</u>	
Scuppers			<u>Bottom, Deck, & Waterways</u>	
Cargo and Main Hatchways			<u>Windlass and Capstan</u>	
Hatches			<u>Pumps</u>	
			<u>Boats</u>	
			<u>Masts, Yards, &c.</u>	
			<u>Condition, how ascertained</u>	
			<u>Sails</u>	
			<u>Anchors, No. of</u>	
			<u>Cables</u>	
			<u>Hawsers and Warps</u>	
			<u>Standing and Running Rigging</u>	

General Observations, Opinion as to Class, &c.
 Committee's Minute 18
 Character assigned
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

