

REPORT of SURVEY for REPAIRS, &c.

No. *28991*(Received at London Office, 19 *5* 8)No. in Survey held at *London*Date, first Survey *9th March* Last Survey *11th March* 18801159 on the *S. S. "Miranda"*Master *A. Key*

YEAR. MONTH.

TONNAGE under Tonnage Deck *855*

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage *996*

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St^rmer, cut on Bm. *736*Built at *Newcastle*When built *1865* *30*Owners *Lon. Ste. Ship Co. (lim)*Port belonging to *London*

Residence

By whom built *Palmer*Destined Voyage *Pessina*Surveyed Afloat *in Dry Dock* *Millwall Dock*
(State Name of Dock)Length of Poop *ft.* Ditto, Forecastle

ft. Ditto, Raised Quarter Deck

ft. Years assigned.

Character in Register Book.

Last Survey, No. *26063*Port *Jm*

Classed

80 A1

REPAIRS, OR EXAMINATION AS PER RULE

3.79

Cause of Repairs to be clearly stated.

S. S. Lon. No 2-77 S. S. Lon. No 3-71

This vessel was surveyed in dry dock & reported in Decbr. last, when some repairs were found necessary, which were not seen after completion. From an examination now made, the above named repairs appear to have been efficiently done; the cement in way of same being found sound & adhering satisfactorily to the iron.

Three short deck planks of raised quarter deck, near boiler casing on each side & 1 tie plate in way of same now renewed.

It is submitted that she is now eligible to have the survey held in Decbr. 1879, recorded.

Special Survey No 3, now nearly due, is intended to be held at the end of this year.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Deerstrakes

Sides

Plates

Hull (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper (or Y.M.)

When put on

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

W. Paulsen

The Amount of Entry Fee ... £ : : received by me, }
Special ... £ : : 18

Certificate (if required)
to be sent as per margin... } £ : :

(Travelling Expenses, if any, £)

Committee's Minute

Tuesday, March, 23rd 1880.

Character assigned

80 A1
12.79

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register
Foundation