

ANNUAL SURVEYS.

26084

No. in Reg. Book. 38946 Survey held at London Date, first Survey Feb 25th Last Survey March 14th 1880
 on the SS Dorunda Master Templeton
 Tonnage 1743 Built at Somerton When built 1875
 By whom built Senny Owners S Macneil & P Senny
 Port belonging to Glasgow Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock

Last Survey, No. 2495 Port of Iran Classed 100A 10.75
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stenson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on new
 Caulking of Bottom, Deck, & Waterways Good
 Windlass and Capstan Good
 Pumps "
 Boats "
 Masts, Yards, &c. "
 Condition, how ascertained From St
 Sails Good
 Anchors, No. of 3 Bbs. St & Redy
 Cables Part on St Good
 Hawseers and Warps "
 Standing and Running Rigging "
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. (Bottom & Coated) Excepting the Prop Bunker the SS M-7 Survey was gone through last October at this Port Report No 24955. The Society's Surveyor at Calcutta as per letter attached has examined the part required & found it in good condition. She is now in an efficient state & eligible to remain as classed & marked SS London No 1-1879 in Register Book.
 Committee's Minute Friday, March 1, 1880 Senhouse Martin
 Character assigned 100A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
TBW S. 8 Nov 79 Certificate (if required) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in Reg. Book. on the Master
 Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
 Last Survey, No. Port of Classed
 Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stenson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Windlass and Capstan
 Pumps
 Boats
 Masts, Yards, &c.
 Condition, how ascertained
 Sails
 Anchors, No. of
 Cables
 Hawseers and Warps
 Standing and Running Rigging
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.
 Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18