

26155

REPORT of SURVEY for REPAIRS, &c.

No. 29032

No. in Survey held at London

Date, first Survey 26th Febr. Last Survey 22nd March 1880

Reg. Book.

124 on the Ship "Pancora" (late White Eagle)

Master R. Power

TONNAGE under Tonnage Deck 756

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage 879

Crew Space, as per Rule

Register Tonnage, cut on Beam 879

Engine Room

Reg. Tons as Stmer, cut on Bm.

Built at Glasgow

When built 1855

Owners New Zealand Ship Co.

Port belonging to London

Residence

By whom built

Destined Voyage Wellington

If Surveyed Afloat or in Dry Dock Canal Dry Dock

Length of Poop ft. Ditto, Forecastle ft.

Ditto, Raised Quarter Deck ft.

Years assigned.

Character in Register Book.

Last Survey, No. 26154

Port

Classed

S. S. Ldn. No 3-73

5.78

REPAIRS, OR EXAMINATION AS PER RULE

S. S. Ldn. No 1-74

Cause of Repairs to be clearly stated.

Several plates, frames & reversed frames in each bow, below upper deck being found considerably wasted, the following Repairs now done:—
Renewed on starboard side 6 plates & 11 ds on port side; 6 frames & 4 rev^d frames partly renewed on each side; 5 frames doubled (partly) on starb^d side & 4⁰⁰ on port side.— Several beam arms riveted; fitted several new liners between frames & plating; collision bulkhead repaired.—
Main mast & upper main topsail yard renewed.—
Pumps repaired.—
Bottom cleaned & repainted.—

Present Condition of the Decks

Good

Freenails Rivets

Good

Windlass and Capstan

Good

Waterways

do

Breasthooks and Stemson

do

Pumps

do

Comings

do

Transoms, Pointers, and Crutches

do

Boats 4 in number

do

Upper Deck Beams & Fastenings

do

Timbers of the Frame at the openings

do

Masts, Yards, &c.

do

Lower Deck Beams & Fastenings

do

Ditto Ditto at other places

do

Condition, how ascertained from deck & enquiry

Planksheers

do

Keelsons

do

Sails

do

Sheerstrakes

do

Clamps and Shelves

do

Anchors No. of 3 B. 1 St. 2 K.

do

Topsides

do

Ceiling

do

Cables part seen

do

Wales

do

Rudder

do

Hawsers and Warps

do

Plank (Bottom) and Counter

do

Copper (or X.M.) Paint

When put on now

Standing & Running Rigging

do

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

do

Cargo and Main Hatchways

good Hatches

do

General Observations, Opinion as to Class, &c.

She is in good condition & eligible in our opinion to remain as classed.—

W. Paulsen

The Amount of Entry Fee ... £ 2 : : : received by me,

14/80 Special ... £ 3 : 3 : 0 16.4.1880

Certificate (if required) to be sent as per margin... £ : :

(Travelling Expenses, if any, £)

Committee's Minute

Fridays, April, 2nd 1880

Character assigned

T.B.W. Apr 80

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation