

REPORT of SURVEY for REPAIRS, &c.

No. 12391

No. in Survey held at Sunderland
Reg. Book.

Date, first Survey 18th March Last Survey 25th March 1880

858 on the Gun Barque "Anglo Norman"

Master Alex^a Davidson

TONNAGE under Tonnage Deck 750

Ditto of Spar Deck, or Avoing Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St^rmer, cut on Bm.

Built at Port Glasgow

When built 1876

Owners Grose, Cook & Co.

Port belonging to London

Residence

By whom built Russell

Destined Voyage East Indies

If Surveyed Afloat & in Dry Dock Graving dock

Length of Poop ft. Ditto, Forecastle

ft. Ditto, Raised Quarter Deck

ft. Years assigned.

Character in Register Book.

Last Survey, No. 21551

Port Shanghai Hon

Classed

100A1

REPAIRS, OR EXAMINATION AS PER RULE S.S. W. 1

Cause of Repairs to be clearly stated.

Now done, The vessel placed upon blocks in dry dock; the timber boards and nearly all the close ceiling on each side lifted and both surfaces of outside plating exposed except the inner surface in way of the Cement in the bottom which was found to be adhering very satisfactory to the inner surface of the shell plating, frames. The outer surface of the shell plating scraped clean and re-coated with 2 coats of paint & 2 lb. of Tallow up to the load line; the floor plates, and reverse bars in flat of bottom coated with cement wash and the ceiling and Hatches in S. re-laid; The whole of the frames, Stingers, Hooks and Crutches, floor plates, Keelsons, Beams, Ribs, Keel, Stem, Stempost & Quads exposed and found in good condition.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plating (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Windlass and Capstan

Pumps Metal

Boats 4 W.

Masts, Yards, &c. As when

Condition, how ascertained

Sails

Anchors No. of 3 lb. 15.2 K

Cables Not seen

Hawsers and Warps

Standing & Running Rigging

Cargo and Main Hatchways

Hatches

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

The Amount of Entry Fee ... £ : : received by me, 11/11

Special ... £ 4 : 4 : 1880

Certificate (if required)

to be sent as per margin... £ - : 5 : -

(Travelling Expenses, if any, £)

Committee's Minute

Friday, April, 9th 1880

Character assigned

100A1
S.S. W. 1

Surveyor to Lloyd's Register of British and Foreign Shipping.

© 2019

Lloyd's Register Foundation

IRON 471-0396