

Report of Survey for Repairs of Engines and Boilers.

No. 281

(Received at London Office, 8/4/80)

No. in Reg. Book. Survey held at *Newcastle* Date, first Survey *22nd March* Last Survey *22nd March* 18*80*
16 on the Machinery of the *S.S. Ulleswater* (Number of Visits *One*)

| | | |
|-------------------------------------|---|---------------------------------|
| Tonnage, Gross <i>908</i> | Built at <i>Sunderland</i> | When built <i>1872</i> |
| Ditto, Net <i>578</i> | Owners <i>H. Strachan</i> | Port belonging to <i>London</i> |
| Diameter of Cylinder <i>26" 48"</i> | Engines made by <i>Geo Clark Sunderland</i> | When made <i>1872</i> |
| Length of Stroke <i>33"</i> | Boilers made by <i>"</i> | When made <i>1872</i> |
| Pressure of Steam <i>60</i> | If Surveyed Afloat or in Dry Dock <i>on Slipway</i> | Classed <i>90 A1</i> |
| Registered Horse Power <i>90</i> | | Years assigned. <i>2,79.</i> |
| Last Survey No. _____ | Port <i>S. S. No. 1-77</i> | |

Particulars of Repairs and Examination of Engines and boilers in accordance with requirements for Special Survey No. 2
Examined sea cocks and propeller while vessel was on Slipway, and found all in good order and in a satisfactory condition

General Observations, Opinion, and Recommendation :—

Entry or Registering Fee ... £ — : — : —

Survey Fee ... £ *1 : 1 : —*

Certificate (if required) ... £ — : — : —

(Travelling Expenses, if any, £ — : — : —)

received by me, *W. S.*
5th April 1880

Committee's Minute *18*

Assigned

Thomas Wilson
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

North Shields

Lloyd's Register
Foundation

IRON 491-0530

It is submitted that
this record is deposite
to remain as
classed

M 8/4/80



© 2019

Lloyd's Register
Foundation