

# REPORT of SURVEY for REPAIRS, &c.

No. 39,102

(Received at London Office, 20.4.80)

No. in Survey held at London

Date, first Survey 5th April Last Survey 15th April 1880

Reg. Book. 192 on the S. S. "Rhône"

Master J. Hestcott

YEAR. MONTH.

TONNAGE under Tonnage Deck 923  
Ditto of Spar Deck, or Awning Deck  
Ditto of Poop  
Ditto of Raised Qr. Dk.  
Ditto of Houses on Deck  
Ditto of Forecastle  
Gross Tonnage 1343  
Crew Space, as per Rule  
Register Tonnage, cut on Beam  
Engine Room  
Reg. Tons as Stmer, cut on Bm. 868

Built at Sunderland When built 1868 2nd

Owners Hestcott & Lawrence Port belonging to London

Residence

By whom built File

Destined Voyage Odessa

Surveyed Afloat in Dry Dock Millwall Dry Dock

(State Name of Dock)

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. Character in Register Book.

Last Survey, No. 25267 Port London Classed 90 A1

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

11.79 S. S. Lon. No 2-79

Repair of Damage through contact with Ice.

On starboard bow renewed 6 plates & on port bow 2 plates, in 1st 2nd & 3rd strakes below sheerstrake. - Partly renewed frames & reversed frames on starb. bow. - Several frames straightened & doubled where damaged. -

Rudder pintles bushed. -

Stop Cleats on rudder renewed. - Propeller renewed. -

One boat repaired. -

Bottom cleaned & repainted. -

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Good

Transoms

Rivets

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper (as per Rule)

Caulking of

Bottom, Deck, & Waterways

Good

Windlass and Capstan

Pumps

Boats 5 in number

Masts, Yards, &c.

Condition, how ascertained from deck enquiry

Sails

Anchors No. of 3 B. 1st. 2nd.

Cables part seen

Hawsers and Warps

Standing & Running Rigging

Cargo and Main Hatchways

Hatches

Good

do

do

do

do

do

do

do

do

do

do

do

do

do

do

do

do

do

do

do

do

do

do

do

do

do

do

do

do

This vessel is in good condition & eligible in my opinion to remain as classed. -

The Amount of Entry Fee ... £ 3 : : received by me,

21/4/80 Special ... £ 1 : 1 : 0 28/4/80

Certificate (if required)

to be sent as per margin... £ 5 : 0

(Travelling Expenses, if any, £ )

Committee's Minute

Character assigned

Friday, April, 23rd 1880

90 A1  
J. Hestcott

Surveyor to Lloyd's Register of British and Foreign Shipping



© 2019

Lloyd's Register Foundation

IRON 492-0040