

Report of Survey for Repairs of Engines and Boilers.

No.

(Received at London Office, 4. 5. 80.)

No. in Reg. Book. Survey held at *London*

Date, first Survey *apl. 26th* Last Survey *April 30th 1880*

4 on the Machinery of the *S. S. "Menzaleh"*

(Number of Visits)

Tonnage, Gross *1618*

Built at *Stockton*

When built *1870*

Ditto, Net *1267*

Owners *Nelson Doulton & Co.*

Port belonging to *London*

Diameter of Cylinder *31 1/2"*

Engines made by *N. E. Marine Co.*

When made *1870*

Length of Stroke *33"*

Boilers made by *N. E. Marine Co.*

When made *1879*

Pressure of Steam *70 lbs.*

If Surveyed Afloat or in Dry Dock *Dry Dock*

Classed *90A1*

Registered Horse Power *130*

Last Survey No.

Port

Shyde M.C. 12.79

Particulars of Repairs and Examination For Annual Survey

Examined sea connections which were found to be in good condition. Propeller examined and found in good condition. New crank shaft fitted 9 1/2" diameter being 1/4" larger than the former one, new brasses throughout & new eccentric sheaves. Examined Forward circulating pump which was damaged at the time of fracture of shaft, repaired with a wrought iron plate fitted on barrel.

General Observations, Opinion, and Recommendation:— *In my opinion this ship is eligible to remain as classed.*

Entry or Registering Fee ... £ — : — :

Survey Fee ... £ — : — :

Certificate (if required) ... £ : :

received by me, 18

(Travelling Expenses, if any, £)

Geo. C. Milnerison
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Friday May 26 1880

Assigned

IRON 492-0202



© 2019

Lloyd's Register Foundation

This vessel machinery has been
surveyed at an arm & survey - Substantiated
that the remains as cleared -

MD 3,450



© 2019

Lloyd's Register
Foundation