

# ANNUAL SURVEYS.

26488  
(Read 23.4.80)

No. 39118 Survey held at London Date, first Survey April 2<sup>d</sup> Last Survey April 22 1880  
 No. in on the SS Taymouth Castle Master J. Fulton  
 Reg. Book. 1172 Tonnage 1827 Built at Glasgow When built 1877-3M  
98 By whom built Barday Owners S. Currie & Co.  
 Port belonging to London Destined Voyage Cape  
 If Surveyed Afloat or in Dry Dock Greens Dry Dock

Last Survey, No. 24778 Port of Iron Classed 100A/10.75  
 Present Condition of the  
 Decks Good Treenails Pivots Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches " Windlass and Capstan Good  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Pumps "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Boats "  
 Planksheers " Keelsons " Masts, Yards, &c. "  
 Sheerstrakes " Clamps and Shelves " Condition, how ascertained From Sts  
 Topsides " Ceiling " Sails Good  
 Wales " Rudder " Anchors, No. of 3 Bw. St & Redgs  
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on Now Cables Part on St Good  
 Caulking of Bottom, Deck, & Waterways Good Hawsers and Warps "  
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "  
 General Observations, Opinion as to Class, &c. Bottom Coated.

*She is now in an efficient state and eligible to remain as Classed*

Committee's Minute Tuesday, April, 27th 1880.  
 Character assigned 100A JTBW  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 1880

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18\_\_\_\_  
 No. in on the \_\_\_\_\_ Master \_\_\_\_\_  
 Reg. Book. \_\_\_\_\_ Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_  
 Present Condition of the  
 Decks \_\_\_\_\_ Treenails \_\_\_\_\_  
 Waterways \_\_\_\_\_ Breasthooks and Stemson \_\_\_\_\_  
 Comings \_\_\_\_\_ Transoms, Pointers, and Crutches \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_ Timbers of the Frame at the Openings \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_ Ditto ditto at other places \_\_\_\_\_  
 Planksheers \_\_\_\_\_ Keelsons \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_ Clamps and Shelves \_\_\_\_\_  
 Topsides \_\_\_\_\_ Ceiling \_\_\_\_\_  
 Wales \_\_\_\_\_ Rudder \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_ Copper or Y.M. \_\_\_\_\_ When put on \_\_\_\_\_  
 Caulking of Bottom, Deck, & Waterways \_\_\_\_\_  
 Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_ Scuppers \_\_\_\_\_ Cargo and Main Hatchways \_\_\_\_\_  
 Hatches \_\_\_\_\_  
 Class, &c. \_\_\_\_\_

\_\_\_\_\_ 18 \_\_\_\_\_  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18 \_\_\_\_\_



FRON 492-0253