

ANNUAL SURVEYS.

26425

No. 39262 Survey held at London Date, first Survey May 21 Last Survey May 24 1880
 No. in the SS Earl King Master W H Pearce
 Reg. Book. 855 Tonnage 1707 Built at Glasgow When built 1865
 By whom built Inglis Owners W Ross & Co
 Port belonging to Glasgow Destined Voyage America
 If Surveyed Afloat or in Dry Dock Pontoon Victoria St

Last Survey, No. 23486 Port of Iran Classed 100A 5.75
 Present Condition of the Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Sides " Ceiling "
 Rudder "
 Copper or Y.M. Copper When put on new
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom to contact.

She is now in good condition and eligible to remain as classed

Committee's Minute Tuesday, June 6th 1880
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 100A 1880
Boilers to be again examined in 6 months

No. 39262 Survey held at London Date, first Survey May 21 Last Survey May 24 1880
 No. in the SS Earl King Master W H Pearce
 Reg. Book. 855 Tonnage 1707 Built at Glasgow When built 1865
 By whom built Inglis Owners W Ross & Co
 Port belonging to Glasgow Destined Voyage America
 If Surveyed Afloat or in Dry Dock Pontoon Victoria St

Last Survey, No. 23486 Port of Iran Classed 100A 5.75
 Present Condition of the Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Sides " Ceiling "
 Rudder "
 Copper or Y.M. Copper When put on new
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom to contact.

Committee's Minute 18
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 100A 1880

