

26732

Report of Survey for Repairs of Engines and Boilers.

No. _____ (Received at London Office, 4.6.80)

No. in Reg. Book. Survey held at London Date, first Survey _____ and Last Survey June 1st 1880

504 on the Machinery of the S. S. Seine (Number of Visits 1)

Tonnage, Gross 3579 Built at London When built 1859 Year

Ditto, Net 2200 Owners Tel. Con. & Maint. Co. Port belonging to London Year

Diameter of Cylinder 60" + 95" Engines made by J. Watt & Co. When made _____ Year

Length of Stroke 48" Boilers made by J. Watt & Co. When made 1873 Year

Pressure of Steam 55 lbs. If Surveyed Afloat or in Dry Dock Dry Dock Classed 100A1 Years assigned _____ Character in Register Book.

Registered Horse Power 500 Last Survey No. _____ Port _____

Lloyds M.C. 2.79

Particulars of Repairs and Examination For Annual Survey

Examined sea connections which were found to be in good condition. Propeller examined, one new blade been fitted. Tail shaft down $\frac{3}{16}$ ".

(Concise and to the point, to be clearly stated.)

General Observations, Opinion, and Recommendation:— In my opinion this ship is eligible to remain as classed.

Entry or Registering Fee ... £ — : — :
Survey Fee ... £ — : — : received by me,
Certificate (if required) ... £ : : 18

(Travelling Expenses, if any, £ _____)

Geo. E. Westinson
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute Friday June 11th 1880

Assigned _____



© 2019 Lloyd's Register Foundation
IRON 492-0608

It is submitted that
this vessel is
eligible to
remain as
classified
M
3/6/88



© 2019

Lloyd's Register
Foundation

Boilers of Engines for Property of Engines and Boilers