

26808
Report of Survey for Repairs of Engines and Boilers.

No.

(Received at London Office, 4. 6. 80)

No. in
Reg. Book.

Survey held at London

Date, first Survey

and

Last Survey June 2nd 1880

1016 on the Machinery of the S. S. "Europa"

(Number of Visits 1)

Tonnage, Gross

676

Built at

Newcastle

When built

1862

Ditto, Net

424

Owners

London Steamship Co.

Port belonging to

London

Diameter of Cylinder

25" x 48"

Engines made by

Palmer

When made

Year

Length of Stroke

30"

Boilers made by

Victoria Eng. Works Co.

When made

1877

Pressure of Steam

75 lbs.

If Surveyed Afloat or in Dry Dock

Pontons

Classed

Years assigned.

Character in Register Book.

95A1

Registered Horse Power

140

Last Survey No.

Port

Lloyd's M.C. 6.79

Particulars of Repairs and Examination For Annual Survey

Examined sea connections which have been overhauled and found to be in good condition. Examined propeller which was in good condition. Tail shaft down 5 1/2"

General Observations, Opinion, and Recommendation:— In my opinion this ship is eligible to remain as classed.

Entry or Registering Fee ... £ — : — :

Survey Fee ... £ — : — :

Certificate (if required) ... £ : :

received by me,

18

(Travelling Expenses, if any, £)

Committee's Minute

Tuesday, June 15th, 1880.

Assigned

Geo. E. Merriam
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register
Foundation

120493-0083

It is submitted that
this vessel is eligible
to remain as
classified

J.M.

3/6/80



© 2019

Lloyd's Register
Foundation

Policy has originated to provide for repairs of Engines and Boilers.