

26895

REPORT of SURVEY for REPAIRS, &c.

Survey held at Birkenhead Date, first Survey June 19 Last Survey July 1 1880
 Name of the Vessel Iron Barge "Arthurstone" Master Wm. [unclear]
 Tonnage under Deck 1052 Built at Dundee When built 1871 - 1880
 of Spar Deck, or Awning Deck
 of Poop
 of Raised Qr. Dk.
 of Houses on Deck
 of Forecastle 1215 Owners J Bruce & Co Port belonging to Dundee
 as Tonnage
 of Space, as per Rule
 Register Tonnage, cut on Beam 1153 By whom built Gowlay Destined Voyage India
 Cabin Room
 Tons as St' mer, cut on Bm.
 If Surveyed Afloat or in Dry Dock Afloat in Great Flow dry dock
 (State Name of Dock)
 Length of Poop 40 ft. Ditto, Forecastle 32 ft. Ditto, Raised Quarter Deck _____ ft. Years assigned. _____ Character in Register Book. 100 A1
 Last Survey, No. 25139 Port Iron Classed _____

REPAIRS, OR EXAMINATION AS PER RULE S J No 1
 Cause of Repairs to be clearly stated.

Not done - The Ceiling equal to two strakes and the lumber boards on each side fore and aft - removed, found the frames, floors, keelsons, plating, rivets, cement etc in good condition, rudders hangers repaired and the hull scraped and painted where required -

Certificate with be called for at the London Office

Present Condition of the Decks	<u>Good</u>	Forecasts	<u>Rivets - Good</u>	Windlass and Capstan	<u>Good & efficient</u>
Waterways	"	Breasthooks and Stanchions	"	Pumps	" "
Comings	"	Transoms, Painters , and Crutches	"	Boats	" "
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	" "
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	<u>Seen from deck</u>
Planksheers	_____	Keelsons	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	_____	Anchors No. of	} <u>Good</u>
Topsides	"	Ceiling	"	Cables	
Wales	"	Rudder	"	Hawsers and Warps	<u>L</u>
Plating (Bottom) and Counter	"	Copper (or Y.M.)	<u>Cem</u> When put on <u>7/5</u>	Standing & Running Rigging	<u>efficient</u>
Engine Room Skylights	_____	Caulking of Bottom, Deck, & Waterways	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>
Coal Bunker, Openings, Lids, &c.	_____	Scuppers	<u>Good</u>	Hatches	<u>Good</u>

General Observations, Opinion as to Class, &c.
This vessel is now in good condition and in my opinion eligible to remain as Classed and marked S J No 1 - 00

The Amount of Entry Fee ... £ : : received by me, J. F. L.
 Special ... £ 4 : 4 : - 2/7/1880
 Certificate (if required) to be sent as per margin... } £ : 5 : -
 Travelling Expenses, if any, £ _____
 Committee's Minute Liverpool July 2-1880
 Character assigned 100 A1. Record SS No 1/80

J. W. Blayell
 Surveyor to Lloyd's Register of British and Foreign Shipping.

The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely in Register Book.

Lloyd's Register Foundation

Arthurstone

27078.



© 2019

Lloyd's Register
Foundation