

# REPORT of SURVEY for REPAIRS, &c.

No. 4878

No. in Survey held at Cardiff

Reg. Book.

Date, first Survey

(Received at London Office, 26/6/80)

Last Survey 22 June 1880

234 on the S.S. Hector

Master J. Lax

TONNAGE under Tonnage Deck 1967  
Ditto of Spar Deck, or Awaiting Deck  
Ditto of Poop  
Ditto of Raised Qr. Dk.  
Ditto of Houses on Deck  
Ditto of Forecastle  
Gross Tonnage 1949  
Crew Space, as per Rule  
Register Tonnage, cut on Beam  
Engine Room  
Reg. Tons as St' mer, cut on Bm. 1534

Built at Sunderland  
Owners E. J. Gourley  
Residence Sunderland  
By whom built Lamin  
If Surveyed Afloat or in Dry Dock East Dute Dock  
(State Name of Dock)

When built 1863 24  
Port belonging to Sunderland  
Destined Voyage New Orleans

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. Character in Register Book.

Last Survey, No. 19880 27199 Port Irony

Classed 90 A1  
SP. Liv. 101. '95  
12.77

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

Now Done

The upper Deck caulked throughout, in accordance with the recommendation of the Society's Surveyor at Sunderland. (See Sunderland Report, No 12426 herewith returned, with sundry other Documents relating to "S.S. No 2." &c.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper (or Y.M.) When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	
Scuppers		
Cargo and Main Hatchways		
Hatches		

General Observations, Opinion as to Class, &c.

So far as seen here, the Vessel appears eligible to remain as classed 90 A1. and to have "S.S. No 2" recorded in the Register Book provided the accompanying Reports are considered satisfactory

The Amount of Entry Fee ...  
Special ...  
Certificate (if required) to be sent as per margin...  
(Travelling Expenses, if any, £)

received by me, held at 48 Sunderland 7/7/80

Henry J. Gurrell  
Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute

Tuesday, June, 29th. 1880

Character assigned

Logis No 6, 80

90 A1  
T.B.W. S.S. No 2 - 80



© 2019  
Lloyd's Register  
Foundation



*S. S. Hector*



© 2019

Lloyd's Register  
Foundation