

# ANNUAL SURVEYS.

27229

No. 29335 Survey held at London Date, first Survey 31 May Last Survey 7 June 1880  
 (Received at London Office, 18/6/80)  
 No. in on the "James Southern" Master Lewis  
 Reg. Book. 95 Tonnage 807 Built at N. Shields When built 1865 5  
 By whom built Smith Owners Wixon & Harris  
 Port belonging to London Destined Voyage Coasting  
 If Surveyed Afloat or in Dry Dock Lincolne dry dock

Last Survey, No. 24587 Port of Iron. Classed 90 A-1  
 Years assigned. 9.79 Character in Register Book. S.S. 4/3.78.  
 Present Condition of the Decks Good  
 Waterways do Treenails Pivets Good  
 Comings do Breasthooks and Stemson do  
 Upper Deck Beams & Fastenings do Transoms, Pointers, and Crutches do  
 Lower Deck Beams & Fastenings do Timbers of the Frame at the Openings do  
 Planksheers do Ditto ditto at other places do  
 Sheerstrakes do Keelsons do  
 Topsides do Clamps and Shelves do  
 Wales do Ceiling do  
 Plank (Bottom) and Counter do Rudder do  
 Engine Room Skylights do Copper or Y.M. ✓ When put on ✓  
 Coal Bunker, Openings, Lids, &c. do Caulking of Bottom, Deck, & Waterways do  
 Scuppers do Cargo and Main Hatchways do Hatches do  
 General Observations, Opinion as to Class, &c.

*Bottom cleaned and recoated. This vessel appears eligible to remain as classed. Rudder pintles bushed. Annexed are the particulars relating to double bottom &c.*

Committee's Minute Tuesday, June, 29th, 1880.  
 Character assigned 90 A-1  
 Surveyor to Lloyd's Register of British and Foreign Shipping. J. H. Bourdow  
 Certificate (if required) 18 Paid 18

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18\_\_\_\_  
 No. in on the \_\_\_\_\_ Master \_\_\_\_\_  
 Reg. Book. \_\_\_\_\_ Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_  
 Years assigned. \_\_\_\_\_ Character in Register Book. \_\_\_\_\_  
 Present Condition of the Decks \_\_\_\_\_  
 Waterways \_\_\_\_\_ Treenails \_\_\_\_\_  
 Comings \_\_\_\_\_ Breasthooks and Stemson \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_ Transoms, Pointers, and Crutches \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_ Timbers of the Frame at the Openings \_\_\_\_\_  
 Planksheers \_\_\_\_\_ Ditto ditto at other places \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_ Keelsons \_\_\_\_\_  
 Topsides \_\_\_\_\_ Clamps and Shelves \_\_\_\_\_  
 Wales \_\_\_\_\_ Ceiling \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_ Rudder \_\_\_\_\_  
 Engine Room Skylights \_\_\_\_\_ Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_ Scuppers \_\_\_\_\_ Cargo and Main Hatchways \_\_\_\_\_ Hatches \_\_\_\_\_  
 General Observations, Opinion as to Class, &c.

Committee's Minute \_\_\_\_\_ 18\_\_\_\_  
 Character assigned \_\_\_\_\_  
 Surveyor to Lloyd's Register of British and Foreign Shipping. \_\_\_\_\_  
 Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18\_\_\_\_

