

ANNUAL SURVEYS.

27249

No. 39442 Survey held at London

Date, first Survey 24 June Last Survey 24 July 1880

No. in Reg. Book. 68 on the R.E. Warrior Tonnage 424 Built at Stockton

Master Thompson

By whom built 487

Owners Thomas

Port belonging to Lpool

Destined Voyage Mauritius

If Surveyed Afloat or in Dry Dock

Limekiln dry dock

Last Survey, No. 13436

Port of Iron

Classed

Years assigned. Character in Register Book.

S.P. No. 3.76.

Present Condition of the

Decks Good

Trenails Rivets Good

Waterways de

Breasthooks and Stemson de

Comings de

Transoms, Pointers, and Crutches de

Upper Deck Beams & Fastenings de

Timbers of the Frame at the Openings de

Lower Deck Beams & Fastenings de

Ditto ditto at other places de

Planksheers de

Keelsons de

Sheerstrakes de

Clamps and Shelves de

Topsides de

Ceiling de

Wales de

Rudder de

Plank (Bottom) and Counter de

Copper or Y.M. When put on

Caulking of Bottom, Deck, & Waterways de

Engine Room Skylights Coal Bunker, Openings, Lids, &c.

Scuppers de

Cargo and Main Hatchways de Hatches de

General Observations, Opinion as to Class, &c.

Bottom cleaned and recoated. Rudder pintles bushed. Sloop renewed. This vessel appears eligible to remain as classed.

Surveyed with ballast in the main hold.

The S.P. No. 1. will be held in vessel's return.

Committee's Minute

Friday, July, 30th 1880

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

No. Survey held at London

Date, first Survey 25 June Last Survey 12 July 1880

No. in Reg. Book. 489 on the R.E. Glenora Tonnage 724 Built at Lpool

Master Scotland

By whom built 696

Owners Shaw, Savill & Co

Port belonging to Southampton

Destined Voyage Auckland

If Surveyed Afloat or in Dry Dock

Bull Head dry dock

Last Survey, No. 23442

Port of Iron

Classed

Years assigned. Character in Register Book.

S.P. No. 3.77.

Present Condition of the

Decks Good

Trenails Rivets Good

Waterways de

Breasthooks and Stemson de

Comings de

Transoms, Pointers, and Crutches de

Upper Deck Beams & Fastenings de

Timbers of the Frame at the Openings de

Lower Deck Beams & Fastenings de

Ditto ditto at other places de

Planksheers de

Keelsons de

Sheerstrakes de

Clamps and Shelves de

Topsides de

Ceiling de

Wales de

Rudder de

Plank (Bottom) and Counter de

Copper or Y.M. When put on

Caulking of Bottom, Deck, & Waterways de

Engine Room Skylights Coal Bunkers, Openings, Lids, &c.

Scuppers de

Cargo and Main Hatchways de Hatches de

General Observations, Opinion as to Class, &c.

Bottom cleaned and recoated. Rudder pintles bushed. This vessel appears eligible to remain as classed.

Committee's Minute

Friday, July, 30th 1880

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

Warr
&
Hendra



© 2019

Lloyd's Register
Foundation