

# ANNUAL SURVEYS. 27256

(Received at London Office, 22. 7. 80)

No. 29430 Survey held at London Date, first Survey July 5<sup>th</sup> Last Survey July 12<sup>th</sup> 1880  
 No. in on the SS Minerva Master \_\_\_\_\_  
 Reg. Book. 098 Tonnage 427 Built at Newcastle When built 1862  
605 By whom built Palmer Owners Sen Steamship Co  
 Port belonging to London Destined Voyage not able to ascertain  
 If Surveyed Afloat or in Dry Dock Porton Victoria Dock

Last Survey, No. 24152 Port of Iron Classed 95A 7-79  
 Years assigned. Character in Register Book.

Present Condition of the Decks	<u>good</u>	Treenails <u>Rivets</u>	<u>good</u>	
Waterways	"	Breasthooks and Stemson	"	Windlass and Capstan <u>good</u>
Comings	"	Transoms, Pointers, and Crutches	"	Pumps
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Boats
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Masts, Yards, &c.
Planksheers	"	Keelsons	"	Condition, how ascertained <u>from st</u>
Sheerstrakes	"	Clamps and Shelves	"	Sails <u>good</u>
Topsides	"	Ceiling	"	Anchors, No. of <u>3 No. st &amp; Redy</u>
Wales	"	Rudder	"	Cables <u>Castle st</u> <u>good</u>
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Canted</u> When put on <u>new</u>	"	Hawsers and Warps
Engine Room Skylights <u>good</u>		Caulking of Bottom, Deck, & Waterways <u>good</u>	"	Standing and Running Rigging
Coal Bunker, Openings, Lids, &c. <u>good</u>		Scuppers <u>good</u>		Cargo and Main Hatchways <u>good</u>
General Observations, Opinion as to Class, &c. <u>Bottom &amp; coats, some rivets renewed</u>				

*She is now in good condition and eligible to remain as classed.*

Committee's Minute Tuesday, July, 27<sup>th</sup> 1880.  
 Character assigned 95A Surveyor to Lloyd's Register of British and Foreign Shipping. Senhouse Martindale  
 Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18 \_\_\_\_\_  
 No. in on the \_\_\_\_\_ Master \_\_\_\_\_  
 Reg. Book. \_\_\_\_\_ Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_  
 Years assigned. Character in Register Book.

Present Condition of the Decks		Treenails		
Waterways		Breasthooks and Stemson		Windlass and Capstan
Comings		Transoms, Pointers, and Crutches		Pumps
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Boats
Lower Deck Beams & Fastenings		Ditto ditto at other places		Masts, Yards, &c.
Planksheers		Keelsons		Condition, how ascertained
Sheerstrakes		Clamps and Shelves		Sails
Topsides		Ceiling		Anchors, No. of
Wales		Rudder		Cables
Plank (Bottom) and Counter		Copper or Y.M. _____ When put on _____		Hawsers and Warps
Engine Room Skylights _____		Caulking of Bottom, Deck, & Waterways _____		Standing and Running Rigging
Coal Bunkers, Openings, Lids, &c. _____		Scuppers _____		Cargo and Main Hatchways _____
General Observations, Opinion as to Class, &c. _____				

Committee's Minute \_\_\_\_\_ 18 \_\_\_\_\_  
 Character assigned \_\_\_\_\_ Surveyor to Lloyd's Register of British and Foreign Shipping. \_\_\_\_\_  
 Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_

