

# REPORT of SURVEY for REPAIRS, &c.

27359

No. 344 in Survey held at Bundee Date, first Survey July 14<sup>th</sup> Last Survey July 24<sup>th</sup> 1880  
 Reg. Book. 104 on the S. Baron Coloway Master Foster  
 TONNAGE under Tonnage Deck 1553 Built at Greenock When built 1875  
 Ditto of Spar Deck, or Awning Deck 1709 Owners J. Mc Cum Port belonging to Greenock  
 Ditto of Poop 1622 Residence Greenock  
 Ditto of Raised Qr. Dk. 1622 By whom built J. E. Scott Destined Voyage Calcutta  
 Ditto of Houses on Deck 1622 If Surveyed Afloat or in Dry Dock Dry Dock  
 Ditto of Forecastle 1622 (State Name of Dock)

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned 100 A 1  
 Last Survey, No. 24759 Port Port Character in Register Book 9.79  
 REPAIRS, OR EXAMINATION AS PER RULE To complete S.S. No 1

Cause of Repairs to be clearly stated.  
 The requirements for this survey were partly carried out in London in Sept. 1879 - See London report 24759 -

The vessel has now been placed in graving dock and the remainder of the vessel opened up for maintenance as required by the lifting of ceiling equal to four strikes on each side on the midship part of the vessel i.e. from just before the main hatch to the water tanks, staff main mast.

The cement was found worn off from one of the landing edges of the bottom & has now been repaired - The remainder of the vessel inside has now been cleaned & recoated and the outside also cleaned & recoated

Present Condition of the	Decks	Waterways	Comings	Upper Deck Beams & Fastenings	Lower Deck Beams & Fastenings	Planksheers	Sheerstrakes	Topsides	Wales	Plank (Bottom) and Counter	Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo and Main Hatchways	Hatches
Decks	good	Transoms	Riveting	good	Windlass and Capstan	complete	good								
Waterways	"	Breasthooks and Stenon	"	"	Pumps	"	"								
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"	"								
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	"	"								
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained	from deck	"								
Planksheers	"	Keelsons	"	"	Sails	good	"								
Sheerstrakes	"	Clamps and Shelves	"	"	Anchors No. of	1/3	15	24							
Topsides	"	Ceiling	"	"	Cables	complete	"								
Wales	"	Rudder	"	"	Hawsers and Warps	"	"								
Plank (Bottom) and Counter	"	Copper (or Lead) Cement - When put on	75	"	Standing & Running Rigging	good	"								
Engine Room Skylights	"	Caulking of	"	"	Cargo and Main Hatchways	good	"								
General Observations, Opinion as to Class, &c.	"	Bottom, Deck, & Waterways	good	"	Hatches	good	"								

The Rules having been complied with & the vessel being in good condition in my opinion to remain as classed & to be marked

S.S. Lon No. 1-79

The Amount of Entry Fee ... £ : : received by me, 9.6  
 Special ... £ 4:4:0 24<sup>th</sup> 1880  
 Certificate (if required) X £ : 5:0  
 to be sent as per margin...

Surveyor to Lloyd's Register of British and Foreign Shipping

(Travelling Expenses, if any, £ )

Committee's Minute

Friday, August 6th, 1880

Character assigned

100A  
 S.S. No. 1-79

© 2019

Lloyd's Register Foundation

IRON 444-0102

ROBT. EDM. TAYLOR & SON, Commercial Steam Printers, 19, Old Street, Goswell Road, London.