

Report of Survey for Repairs of Engines and Boilers.

27365
 (Received at London Office, 26/7/80)

No. 157
 Survey held at Leamth, Ceto Date, first Survey _____ Last Survey 2nd June 1880
 No. in Book. _____ (Number of Visits 1)
78 on the Machinery of the _____
 Tonnage, Gross 970 Built at Stockton When built 1878
 Ditto, Net 812 Owners H. Cloake Port belonging to London
 Diameter of Cylinder 26 1/2 x 49 Engines made by Blair & Co (Lin) When made 1878
 Length of Stroke 33 Boilers made by _____ When made 1878
 Pressure of Steam 70 Surveyed Afloat in Dry Dock _____
 Registered Horse Power 95 Classed 100 A1
 Last Survey No. 21113 Port Lon Years assigned 7.79 Character in Register Book.

Particulars of Repairs and Examination

A new crankshaft fitted.

General Observations, Opinion, and Recommendation:— The Machinery is now in good condition and safe working order and in my opinion eligible to remain as classed.

Entry or Registering Fee ... £ :
 Survey Fee ... £ 1 : 1 : received by me, [Signature]
 Certificate (if required) ... £ : : 21st July 1880
 Travelling Expenses, if any, £ - 5/-

[Signature]
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Assigned



Insert Character precisely as in the Register Book.

IRON 494 - 0111

Submitted that this account
is eligible to remain ad-
closed-

MP
26.7.80

M. L. L. L.



© 2019
Lloyd's Register
Foundation