

27379

# Report of Survey for Repairs of Engines and Boilers.

No. \_\_\_\_\_ (Received at London Office, 4. 8. 80)

Survey held at London Date, first Survey and Last Survey July 14<sup>th</sup> 1880

"66" on the Machinery of the S. S. "Eldorado" (Number of Visits 1)

Tonnage, Gross <u>3332</u>	Built at <u>Hull</u>	When built <u>1873</u>
Ditto, Net <u>2157</u>	Owners <u>A. Gray &amp; E. S. Dawes</u>	Port belonging to <u>Glasgow</u>
Diameter of Cylinder <u>47" + 90"</u>	Engines made by <u>Charles' Co.</u>	When made <u>1873</u>
Length of Stroke <u>50"</u>	Boilers made by <u>Charles' Co.</u>	When made <u>1873</u>
Pressure of Steam <u>60 lbs.</u>	If Surveyed Afloat or in Dry Dock <u>On Pontoon</u>	Classed <u>100 A1</u>
Registered Horse Power <u>450</u>		Years assigned <u>100</u>
Last Survey No. _____	Port _____	Character in Register Book <u>Lloyds M.C. 7.78</u>

## Particulars of Repairs and Examination For Annual Survey

Examined sea connections which were found to be in good condition. Propeller examined & found in good condition. The After crank has had a  $5\frac{1}{2}$  hole bored through it and a steel pin fitted.

General Observations, Opinion, and Recommendation:— In my opinion this ship is eligible to remain as Classed.

Entry or Registering Fee ... £ : :  
Survey Fee ... £ — : — : received by me,  
Certificate (if required) ... £ : : 188


(Travelling Expenses, if any, £ )

Committee's Minute

Friday, August 6th. 1880

Assigned

Geo. E. Milner  
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2019

Lloyd's Register  
Foundation

IRON 494-0131



It is submitted that this  
vessel is eligible to  
remain a  
classed.

JM

3/8/85



© 2019

Lloyd's Register  
Foundation