

REPORT of SURVEY for REPAIRS, &c.

24465

No. 27/31 Survey held at Liverpool Date, first Survey July 19th Last Survey July 23rd 1880
 Reg. Book. 73 on the Ship "Bann" Master A. E. Rae
 Official Number 73550
 TONNAGE under Tonnage Deck 1567
 Ditto of Spar Deck or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage 1719
 Crew Space, as per Rule
 Register Tonnage, cut on Beam 1650
 Engine Room
 Reg. Tons as St' mer, cut on Bm.
 Built at Sunderland When built 1875 - 7
 Owners J. Nourse Port belonging to London
 Residence London
 By whom built Gwald Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Mercurianum Dry Dock
 (State Name of Dock)
 Length of Poop 50 ft. Ditto, Forecastle 40 ft. Ditto, Raised Quarter Deck ✓ ft.
 Last Survey, No. 27464 Port London Classed 100 A1
 REPAIRS, OR EXAMINATION AS PER RULE
 Cause of Repairs to be clearly stated.

S. S. N^o 1 (Completion)
 Vessel placed in dry dock, bottom examined
 cleaned and coated with paint.
 Mid-section inside now examined as follows:—
 Limbers and ceiling equal to the requirements
 of the Rules lifted, cement with floors, frames
 &c found in a satisfactory condition.
 The distance of the hold on the fore and aft
 side of this space was covered with outward
 cargo, but was stated by the Master to have been
 examined by a Surveyor to this Society before
 the cargo was taken in — while laying at Greenock.
 p. T. O.

Present Condition of the	Good	Treenails	Rivets	Good	Windlass and Capstan	Good
Decks	✓	Breasthooks and Stems	✓	✓	Pumps	✓
Waterways	✓	Transoms, Pointers, and Crutches	✓	✓	Boats	✓
Comings	✓	Timbers of the Frame at the openings	✓	✓	Masts, Yards, &c.	✓
Upper Deck Beams & Fastenings	✓	Ditto Ditto at other places	✓	✓	Condition, how ascertained	from on board
Lower Deck Beams & Fastenings	✓	Keelsons	✓	✓	Sails	Good
Plank sheers	✓	Clamps and Shells	✓	✓	Anchors No. of	3 B - 18 - 2 K
Sheerstrakes	✓	Ceiling	✓	✓	Cables	pt. seen } Good
Topsides	✓	Rudder	✓	✓	Hawsers and Warps	and
Wales	✓	Copper for R.M. Cement When put on	75	✓	Standing & Running Rigging	Sufficient.
Plank (Bottom) and Counter	✓	Caulking of	Good	✓	Cargo and Main Hatchways	Good
Engine Room Skylights	✓	Bottom, Deck, & Waterways	Good	✓	Hatches	Good
Coal Bunker, Openings, Lids, &c.	✓	Scuppers	Good	✓		

General Observations, Opinion as to Class, &c.

This vessel is now in a good and efficient condition, and the above examination, completing the survey having been held; she is eligible in my opinion to remain as Classed and to be now marked
S. S. L^o N^o 1. 80.

The Amount of Entry Fee ... £ : : received by me, J. F. L.
 Special ... £ 2 : 2 : 0 14/9/80
 Certificate (if required) } £ : :
 to be sent as per margin...

J. Shilstone
 Surveyor to Lloyd's Register of British and Foreign Shipping

(Travelling Expenses, if any, £)

Committee's Minute Liverpool Aug. 13th 1880

Character assigned 100 A1. Record S S N^o 1/80



© 2019
 Lloyd's Register
 Foundation

27465
Having examined the Greenock Report N^o 7831.
regarding this vessel, it appears that the
survey here completes the requirements
for S. S. N^o 1.

J. Shilstone.

27131

J. Shilstone.



© 2019

Lloyd's Register
Foundation