

REPORT of SURVEY for REPAIRS, &c.

No. 29482

No. in Survey held at
Reg. Book.

London

Date, first Survey

19th July

(Received at London Office, August 10th. 80.)
Last Survey 29th July 1880

1039 on the

S. "Collingwood"

Master Forbes

YEAR.

MONTH.

TONNAGE under Tonnage Deck
Ditto of Spar Deck, or Awning Deck
Ditto of Poop
Ditto of Raised Qr. Dk.
Ditto of Houses on Deck
Ditto of Forecastle
Gross Tonnage
Crew Space, as per Rule
Register Tonnage, cut on Beam
Engine Room
Reg. Tons as St' mer, cut on Bm.

Built at

Aberdeen

When built

1872

Owners

Dewett & Moore

Port belonging to

London

Residence

By whom built

Good

Destined Voyage

Melbourne

If Surveyed Afloat or in Dry Dock
(State Name of Dock)

Nelson Dry Dock

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No.

24698

Port

S. S. N^o 2

Classed

S. S. N^o 1-77

100 A1

10-77

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

Vessel placed in dry dock, bottom cleaned and recoated with paint, the timbers and three strakes of ceiling fore and aft on each side removed, cement on inner surface of bottom plating tested and found adhering satisfactorily to the iron - Oxidation on ironwork removed, and recoated with cement wash where required. Windlass lining partly stripped & examined, cables ranged on deck and found complete. Mast & spars examined and found in good condition with the exception of Main & fore upper topsail yards, which have now been renewed.

Present Condition of the

Decks

Good

Treenails Rivets

Good

Windlass and Capstan

Good

Waterways

Breasthooks and Stemson

Pumps

Comings

Transoms, Pointers, and Crutches

Boats 4 in N^o

Upper Deck Beams & Fastenings

Timbers of the Frame at the openings

Masts, Yards, &c.

Lower Deck Beams & Fastenings

Ditto Ditto at other places

Condition, how ascertained by examination

Planksheers

Keelsons

Sails Complete

Good

Sheerstrakes

Clamps and Shelves

Anchors No. of 313. 18 & 2 K

Topsides

Ceiling

Cables Complete

Wales

Rudder

Hawsers and Warps

Plank (Bottom) and Counter

Copper (or Y.M.) paint When put on now

Standing & Running Rigging

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

This vessel is now in good condition the requirements of the above survey have been complied with, and she is in our opinion eligible to remain as classed, and to have recorded S. S. N^o 2-80-

The Amount of Entry Fee ... £ " : " : " received by me,

1/8/80 Special ... £ 4 : 4 : 1/8/80

Certificate (if required)

to be sent as per margin...

(Travelling Expenses, if any, £)

Committee's Minute

Friday, August 13th. 1880

Character assigned

100

S. S. N^o 2-80



© 2019

Lloyd's Register Foundation