

ANNUAL SURVEYS.

(Received at London Office, 1880)

No. 14999 Survey held at South Shields Date, first Survey 26 August Last Survey 26 Aug 1880
 No. in on the S.S. "Birling" Master Hanson
 Reg. Book. Tonnage 95 1/2 Built at South Shields When built 1872 - 9 mo
 By whom built Edgingham Owners J. Brown & Co.
 Port belonging to London Destined Voyage Coasting
 If Surveyed Afloat or in Dry Dock Newcastle's Dock

Last Survey, No. 24659 Port of Iron

Classed

Years assigned.

Character in Register Book.

90 A 1

9-49

Present Condition of the

Decks Good

Waterways "

Comings "

Upper Deck Beams & Fastenings "

Lower Deck Beams & Fastenings "

Planksheers "

Sheerstrakes "

Topsides "

Wales "

Plank (Bottom) and Counter Not Seen

Engine Room Skylights Good

General Observations, Opinion as to Class, &c.

Rivets Good

Breasthooks and Stemson Not Seen

Transoms, Pointers, and Crutches "

Timbers of the Frame at the Openings Good

Ditto ditto at other places "

Keelsons "

Clamps and Shelves "

Ceiling "

Rudder "

Cement When put on 12

Caulking of Bottom, Deck, & Waterways Good

S.S. No 1-44

Windlass and Capstan

Pumps Metal

Boats 3 h.

Masts, Yards, &c. when

Condition, how ascertained

Sails

Anchors, No. of 3 B. 15. 1 K

Cables Not Seen

Hawsers and Warps

Standing and Running Rigging

Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 The pumps of the dock having broken down the water could not be pumped out so as to admit of the bottom being sighted. Several timbers lifted & cement examined; the vessel appears in good & efficient condition & eligible in my opinion to remain as classed.

Intimated to the Captain that his vessel was eligible for S.S. W. 2. but he states that he is coming into dock to receive new boiler in about 2 months
 Committee's Minute Tuesday, September, 14th 1880.

Character assigned

90 A 1

James Gibson

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

No. Survey held at South Shields Date, first Survey 1 Sept. Last Survey 1 Sept. 1880

No. in on the S.S. "Neworth Castle" Master R. Hutton
 Reg. Book. Tonnage 134 1/2 Built at Sunderland When built 1878 - 3 mo
 By whom built Thompson Owners G. Watson
 Port belonging to Sunderland Destined Voyage Genoa
 If Surveyed Afloat or in Dry Dock Middle Dock

Last Survey, No. 22764 Port of Iron

Classed

Years assigned.

Character in Register Book.

100 A 1

1-49

Present Condition of the

Decks Good

Waterways "

Comings "

Upper Deck Beams & Fastenings "

Lower Deck Beams & Fastenings "

Planksheers "

Sheerstrakes "

Topsides "

Wales "

Plank (Bottom) and Counter "

Engine Room Skylights Good

General Observations, Opinion as to Class, &c.

Rivets Good

Breasthooks and Stemson Not Seen

Transoms, Pointers, and Crutches "

Timbers of the Frame at the Openings Good

Ditto ditto at other places "

Keelsons "

Clamps and Shelves "

Ceiling "

Rudder "

Cement When put on 78

Caulking of Bottom, Deck, & Waterways Good

Windlass and Capstan

Pumps Metal

Boats 4 h.

Masts, Yards, &c. when

Condition, how ascertained

Sails

Anchors, No. of 3 B. 15. 2 K

Cables Not Seen

Hawsers and Warps

Standing and Running Rigging

Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 Sighted Bottom; The outer shell plating coated with 2 coats of Dammatt's Pat. composition up to about 12 feet and 1 coat of paint above to the gunwale. The vessel is now in good & efficient condition & eligible in my opinion to remain as classed.

Committee's Minute

Tuesday, September, 14th 1880.

Character assigned

100 A 1

James Gibson

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18