

ANNUAL SURVEYS.

27670

No. 39566 Survey held at London Date, first Survey 26th August Last Survey 27th August 1880
No. in on the Iron Scw. Sr. "Blenheim." Master E. Gillings.
Reg. Book. 545 Tonnage 735 Built at Hartlepool. When built 1877-10 mo.
By whom built Witby. Owners Steel, Young & Co.
Port belonging to London Destined Voyage British Guiana.
If Surveyed Afloat or in Dry Dock In West India Dry Dock.

Last Survey, No. 25696 Port of London Classed 90 A.1.
Years assigned. 2. 80 Character in Register Book.

Present Condition of the

Decks	<u>good</u>	Treenails	<u>rivets</u>	<u>good</u>
Waterways	<u>do</u>	Breasthooks and Stemson		<u>do</u>
Comings	<u>do</u>	Transoms, Pointers , and Crutches		<u>do</u>
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the Openings		<u>do</u>
Lower Deck Beams & Fastenings	<u>do</u>	Ditto ditto at other places		<u>do</u>
Planksheers	<u>do</u>	Keelsons		<u>do</u>
Sheerstrakes	<u>do</u>	Clamps and Shelves		<u>do</u>
Topsides	<u>do</u>	Ceiling		<u>do</u>
Wales	<u>do</u>	Rudder		<u>do</u>
Plating (Bottom) and Counter	<u>do</u>	Copper or Y.M.	<u>When put on</u>	
Engine Room Skylights	<u>good</u>	Caulking of Bottom, Deck, & Waterways	<u>good</u>	
Coal Bunker, Openings, Lids, &c.	<u>good</u>	Scuppers	<u>good</u>	
General Observations, Opinion as to Class, &c.		Cargo and Main Hatchways	<u>good</u>	
		Hatches	<u>good</u>	

Windlass and Capstan good
Pumps do
Boats do
Masts, Yards, &c. do
Condition, how ascertained from the deck
Sails good
Anchors, No. of 3 B. 1 L. 2 K.
Cables complete
Hawsers and Warps sufficient
Standing and Running Rigging do

The bottom has been examined, cleaned & coated. The rudder pintles rebushed.
This vessel appears to be eligible to remain as classed.

Committee's Minute Friday, September 3rd. 1880

Character assigned 90 A.1 J.H. Truscott.
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18

No. Survey held at Date, first Survey Last Survey 18
No. in on the Master
Reg. Book. Tonnage Built at When built
By whom built Owners
Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed
Years assigned. Character in Register Book.

Present Condition of the

Decks		Treenails		
Waterways		Breasthooks and Stemson		Windlass and Capstan
Comings		Transoms, Pointers, and Crutches		Pumps
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Boats
Lower Deck Beams & Fastenings		Ditto ditto at other places		Masts, Yards, &c.
Planksheers		Keelsons		Condition, how ascertained
Sheerstrakes		Clamps and Shelves		Sails
Topsides		Ceiling		Anchors, No. of
Wales		Rudder		Cables
Plank (Bottom) and Counter		Copper or Y.M.	<u>When put on</u>	Hawsers and Warps
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways		Standing and Running Rigging
Coal Bunkers, Openings, Lids, &c.		Scuppers		Hatches
General Observations, Opinion as to Class, &c.				

Committee's Minute 18

Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18