

ANNUAL SURVEYS. 2782

(Received at London Office, B. 2. 2. 80.)

No. 34637 Survey held at London Date, first Survey and Last Survey 9. Sept. 1880
 No. in on the V. S. "Lorne" Master Reed
 Reg. Book. 744 Tonnage 763 Built at Stull When built 1873
918 By whom built Gilbert Owners Bailey & Leatham
 Port belonging to Stull Destined Voyage —
 If Surveyed Afloat or in Dry Dock Union Dry Dock

Last Survey, No. 24710 Port of Iron Classed 90 A 1
 Present Condition of the Decks Good Treenails Pivots Good S. S. L. No. 1. 78. 10. 79
 Waterways — Breasthooks and Stemson — Windlass and Capstan Good
 Comings — Transoms, Pointers, and Crutches — Pumps Complete & —
 Upper Deck Beams & Fastenings — ~~Timbers of the Frame at the Openings~~ — Boats 5 in No 2 —
 Lower Deck Beams & Fastenings — Ditto ditto at other places — Masts, Yards, &c. —
 Planksheers — Keelsons — Condition, how ascertained from deck
 Sheerstrakes — Clamps and Shelves — Sails Complete & good
 Topsides — Ceiling — Anchors, No. of 3 B. 1 S. 2 K
 Wales — Rudder — Cables Complete
 Plank (Bottom) and Counter — Copper or Y.M. Coating When put on 80 Hawfers and Warps —
 Caulking of Bottom, Deck, & Waterways Good Standing and Running Rigging — & good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers — Cargo and Main Hatchways Good Hatches —

General Observations, Opinion as to Class, &c.
The vessel has been examined in Dry dock, bottom cleaned, timber boards lifted & all found in good condition. She is eligible, in my opinion, to continue as classed.

Committee's Minute Tuesday, September, 28th 18 80.
 Character assigned GOOD
 Surveyor to Lloyd's Register of British and Foreign Shipping, James Surpin
 Certificate (if required) — Paid — 18 —

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____
 No. in on the _____ Master _____
 Reg. Book. _____ Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____
 Present Condition of the Decks _____
 Waterways _____ Treenails _____
 Comings _____ Breasthooks and Stemson _____
 Upper Deck Beams & Fastenings _____ Transoms, Pointers, and Crutches _____
 Lower Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Planksheers _____ Ditto ditto at other places _____
 Sheerstrakes _____ Keelsons _____
 Topsides _____ Clamps and Shelves _____
 Wales _____ Ceiling _____
 Plank (Bottom) and Counter _____ Rudder _____
 Copper or Y.M. _____ When put on _____
 Caulking of Bottom, Deck, & Waterways _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18 _____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping, _____
 Certificate (if required) _____ Paid _____ 18 _____



IRON 495-0143