

ANNUAL SURVEYS.

24963

(Received at London Office, (Reg'd 16th 10 80.)

No. 24963 Survey held at London Date, first Survey Oct 4th Last Survey Oct 15 1880
 No. in on the BK Adamant Master J Bowling
 Reg. Book. 26 Tonnage 815 Built at Hull When built 1858
 By whom built _____ Owners Shaw Savill & Co
 Port belonging to Southampton Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock Green's Dry Dock

Last Survey, No. 24048 Port of Ton

Classed AT 7-75
SS Linmar
S.S. No. 3-71

Present Condition of the Decks	<u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>
Waterways	"	Breasthooks and Stemson	"
Comings	"	Transoms, Pointers, and Crutches	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"
Planksheers	"	Keelsons	"
Sheerstrakes	"	Clamps and Shelves	"
Topsides	"	Ceiling	"
Wales	"	Rudder <u>New Rudder Pins</u>	"
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Copper</u> When put on <u>Nov</u>	"
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways	<u>Good</u>
Coal Bunker, Openings, Lids, &c.		Scuppers <u>Good</u>	
General Observations, Opinion as to Class, &c.		Cargo and Main Hatchways <u>Good</u>	
		Hatches	"

Windlass and Capstan Good
 Pumps "
 Boats "
 Masts, Yards, &c. "
 Condition, how ascertained From Stk
 Sails Good
 Anchors, No. of 3 Bns H & Pags
 Cables Part on Stk Good
 Hawesers and Warps "
 Standing and Running Rigging "

Bottom in course
She is now in good condition
and eligible to remain as classed

Committee's Minute Tuesday, October, 19th 1880.

Character assigned * A 1
TTBW

Senhouse Martin
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____
 No. in on the _____ Reg. Book. _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____

Classed _____

Present Condition of the Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors, No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawesers and Warps
Plank (Bottom) and Counter	Copper or Y.M. _____ When put on _____	Standing and Running Rigging
Engine Room Skylights	Caulking of Bottom, Deck, & Waterways	Hatches
Coal Bunkers, Openings, Lids, &c.	Scuppers	
General Observations, Opinion as to Class, &c.	Cargo and Main Hatchways	

Committee's Minute Tuesday, October, 19th 1880.

Character assigned _____

Senhouse Martin
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

