

Report of Survey for Repairs of Engines and Boilers.

(Received at London Office, (Rec'd 19th 10 80.))

No. in Survey held at London Date, first Survey and Last Survey Oct. 7th 1880
g. Book. 395 on the Machinery of the S. S. "Dorunda" (Number of Visits 1)
Year
Tonnage, Gross 2977 Built at Dumbarton When built 1875
Ditto, Net 1943 Owners A. Macnail & P. Denny Port belonging to Glasgow
Diameter of Cylinder 47" x 82" Engines made by Denny & Co. When made 1875
Length of Stroke 48" Boilers made by Ditto When made 1875
Pressure of Steam 65 lbs. If Surveyed Afloat or in Dry Dock On Pontoon Classed 100A1
Registered Horse Power 400 Lloyds M.C. 10.79
Last Survey No. Port

Particulars of Repairs and Examination For Annual Survey -

Vessel placed on Pontoon. All sea connections examined and found to be in good condition. Tail shaft found to be down nearly $\frac{3}{8}$ ". Propeller disconnected and new lignum vitae fitted in stern bush, & the propeller refitted.

General Observations, Opinion, and Recommendation:— As far as seen this ship appears eligible to remain as classed.

Entry or Registering Fee ... £ : :
Survey Fee ... £ : : received by me, }
Certificate (if required) ... £ : : 188 }
(Travelling Expenses, if any, £)

Committee's Minute

Friday, October 22nd 1880

Assigned

Geo. E. Milner
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register
Foundation

120495-0606

It is submitted that this
vessel is eligible to
remain as classed

Jm
18/10/80



© 2019

Lloyd's Register
Foundation