

Report of Survey for Repairs of Engines and Boilers.

(Revised 1878)

No. _____
 No. in Reg. Book. Survey held at London Date, first Survey _____ Last Survey 17 April 1878
1195 on the S. S. Mirfield Master _____
 Tons 867 Owners J. B. Crawhall Port belonging to London Classified _____ Years assigned _____ Character in Register Book. 100 A 1


Diameter of Cylinder 23 1/2 Engines made at Greenock When made 1841
 Length of Stroke 30 Pressure of Steam 65 By whom made Greenock Foundry Co.
 Registered Horse Power 120

Particulars of Repairs and Examination, The airpipes to after tank have been taken off, the forward one in tunnel fitted with brass screw plug the others flanked up with 3/8 iron flanges, in accordance with recommendations in Report of _____
Monkey Boiler now examined and found in good condition Main boilers have been fitted with Adams patent safety valves which are in accordance with the Societys Rules. The machinery appears now to be in good order and safe working condition

The Amount of Fee 22/6/0 2 : 2 : 0 received by me, _____
 Certificate (if required) ... £ : : 30 Sep 1878

James Milton
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute _____ 3rd. May. 1878.



© 2019
 Lloyd's Register
 Foundation

It is submitted that this vessel
is now eligible to have entry
granted and Lloyd's Dec 4, 78
recorded
M 10/4/78



© 2019

Lloyd's Register
Foundation